



U.S. Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: I-2007120092
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident:
10/30/2007
4. Time of Incident (use 24-hour time):
09:19
5. Enter National Response Center Report Number (if applicable):
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
- City: DALTON
County: WHITFIELD
State: GA
Zip Code: (if known): 30720
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
VD PARROTT PKWY.
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
- Name: PEACH STATE LABS, INC.
Street: 180 BURLINGTON ROAD
City: ROME
State: GA
Zip Code: 30161
Federal DOT Id Number: 366314
Hazmat Registration Number: 062907003023P
11. Shipper/Offendor:
- Name: PEACH STATE LABS, INC.
Street: 180 BURLINGTON ROAD
City: ROME
State: GA
Zip Code: 30161
Waybill/Shipping Paper: 27196
Hazmat Registration Number: 062907003023P
12. Origin (if different from shipper address)
- Street:
City:
State:
Zip Code:
13. Destination:
- Street: 501 EAST FRANKLIN ST
City: DALTON
State: GA
Zip Code: 30722
14. Proper Shipping Name of Hazardous Material: CORROSIVE LIQUID, ACIDIC, ORGANIC, N.O.S.
15. Technical/Trade Name: AUTOACID
16. Hazardous Class/Division: Corrosive Material
17. Identification Number: (E.g. UN2764, NA 2020) UN3265

- 18. Packing Group:** (if applicable) II
- 19. Quantity Released:** (Include Measurement Units) 200 Liquid - Gallon
- 20. Was the material shipped as a hazardous waste?** False
If yes, provide the EPA Manifest Number:
- 21. Is this a Toxic by Inhalation (TIH) material?** False
If yes, provide the Hazard Zone:
- 22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate?** False
If yes, provide the Exemption, Approval, or CA number:
- 23. Was this an undeclared hazardous materials shipment?** False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:
IBC

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: - 109-Closure (e.g., Cap, Top, or Plug); 136-Locking Bar

How Failed: - 312-Torn Off or Damaged; 312-Torn Off or Damaged

Causes of Failure: - Dropped; Incorrectly Sized Component or Device

26a. Provide the packaging identification markings, if available.

Identification Markings: UN31HA1/Y/UB7USA/SCHUTZ4/++AA2503/4620/

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Packaging Type: Material of Construction: Head Type (Drums only):	Packaging Type: Material of Construction:
27. Describe the package capacity and the quantity:	
Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Package Capacity: 275 Liquid - Gallon Amount in Package: 252 Liquid - Gallon Number in Shipment: 6 Number Failed: 3	Package Capacity: Amount in Package: Number in Shipment: Number Failed:
28. Provide packaging construction and test information, as appropriate: Manufacturer: Serial Number: Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder) Design Pressure: (if Tank Car, CTMV, Portable Tank) Shell Thickness: (if Tank Car, CTMV, Portable Tank) Head Thickness: (if Tank Car, CTMV) Service Pressure: (if Cylinder) If valve or device failed: Type: Model: Manufacturer:	
29. If the packaging is for Radioactive Materials, complete the following: Packaging Category: Packaging Certification: Certification Number: Nuclide(s) Present: Activity: Critical Safety Index:	

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | False |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

Fire/EMS Report #: True 07-0001214
Police Report #: False
In-house cleanup: False
Other Cleanup: False

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 221.00
Carrier Damage: \$ 1,000.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 10,000.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees: 0
Responders: 0
General Public: 0

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many? 0

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees: 0
Responders: 0
General Public: 0

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees: 0
Responders: 0
General Public: 0

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated:
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

False

If yes, how many?

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

Peach State Labs, Inc. was delivering IBCs to various customers in Dalton, GA. After the first delivery, at approximately 9:19 a.m. our driver was detoured to a non-typical route due to road construction. This route included a large hill at the north end of VD Parrot Pkwy. After stopping for traffic, the driver accelerated causing the tractor to shake. This shaking caused 3 - 275 gallon IBCs of Autoacid A-80-N to shift in the truck breaking the load lock and sliding out of the truck onto the road. Driver immediately circled back around and contacted 911. 2 of the 3 IBCs were leaking from the top closure and significant damage was noted on all IBCs from fall. Dalton Fire Department responded to contain leaking product. Marion Environmental Services responded on behalf of carrier to perform remediation and cleanup. Approximately 200 gallons of Autoacid A-80-N leaked. The spill was neutralized and cleaned up by Marion Environmental Services.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

Peach State Labs, Inc. has purchased additional higher capacity load locking devices and has revised box truck loading procedures to ensure against future load shifts. The leakage from the IBCs was minimal considering damage sustained during fall. No corrective actions are necessary for IBCs.

PART VIII – CONTACT INFORMATION

Contact's Name:	KERRY BARNETT
Contact's Title:	EHS SPECIALIST
Business Name and Address:	PEACH STATE LABS INC 180 BURLINGTON ROAD ROME GA 30161
E-mail Address:	kbarnett@peachstatelabs.com
Telephone Number:	706-291-8743
Fax Number:	706-291-4888
Hazmat Registration Number:	062907003023P
Date:	11/27/2007
Preparer is:	Carrier