



U.S. Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: I-2022080013
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/13/2022
4. Time of Incident (use 24-hour time): 09:48
5. Enter National Response Center Report Number (if applicable):
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: BEAVER DAM
County: DODGE
State: WI
Zip Code: (if known): 53916
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
Hemlock Rd 1 mile east Hwy 151
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: WAYNE TRANSPORTS, INC.
Street: 14345 CONLEY AVE
City: ROSEMOUNT
State: MN
Zip Code: 55068-4441
Federal DOT Id Number: 166179
Hazmat Registration Number: 041921550004DF
11. Shipper/Officer:
Name: UNITED WISCONSIN GRAIN PRODUCERS, LLC
Street: W1231 TESSMAN DR
City: FRIESLAND
State: WI
Zip Code: 53923-9510
Waybill/Shipping Paper:
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: 4240 HWY 26 NORTH
City: WAUPUN
State: WI
Zip Code: 53963
14. Proper Shipping Name of Hazardous Material: ALCOHOLS, N.O.S.
15. Technical/Trade Name:
16. Hazardous Class/Division: Flammable - Combustible Liquid
17. Identification Number: (E.g. UN2764, NA 2020) UN1987

18. Packing Group: (if applicable)

19. Quantity Released: (Include Measurement Units) 4263 Liquid - Gallon

20. Was the material shipped as a hazardous waste? False

If yes, provide the EPA Manifest Number:

21. Is this a Toxic by Inhalation (TIH) material? False

If yes, provide the Hazard Zone:

22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate? False

If yes, provide the Exemption, Approval, or CA number:

23. Was this an undeclared hazardous materials shipment? False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:

Cargo Tank Motor Vehicle (CTMV)

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: -

How Failed: -

Causes of Failure: -

26a. Provide the packaging identification markings, if available.

Identification Markings: DOT406

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Packaging Type:

Material of Construction:

Head Type (Drums only):

Packaging Type:

Material of Construction:

27. Describe the package capacity and the quantity:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Package Capacity: 9500 Liquid - Gallon

Amount in Package: 8210 Liquid - Gallon

Number in Shipment: 1

Number Failed: 1

Package Capacity:

Amount in Package:

Number in Shipment:

Number Failed:

28. Provide packaging construction and test information, as appropriate:

Manufacturer: LBT, INC

Serial Number: 4J8704322DT00010

Material of Construction: 5454H32ALUMINUM (if Tank Car, CTMV, Portable Tank, or Cylinder)

Design Pressure: 3.3 PSI (if Tank Car, CTMV, Portable Tank)

Shell Thickness: 173 INCH (if Tank Car, CTMV, Portable Tank)

Head Thickness: 0.173 INCH (if Tank Car, CTMV)

Service Pressure: (if Cylinder)

If valve or device failed:

Type:

Model:

Manufacturer:

Manufacture Date: 06/25/2012

Last Test Date: 07/09/2021

29. If the packaging is for Radioactive Materials, complete the following:

Packaging Category:

Packaging Certification:

Certification Number:

Nuclide(s) Present:

Activity:

Critical Safety Index:

Transport Index:

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | |
|---------------------------|--|
| - Spillage: True | - Fire: False |
| - Explosion: | - Material Entered Waterway/Storm Sewer: |
| - Vapor (Gas) Dispersion: | - Environmental Damage: |
| - No Release: False | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

Fire/EMS Report #: True 2205123
Police Report #:
In-house cleanup:
Other Cleanup:

32. Damages Was the total damage cost more than \$500? True

If yes, enter the following information: (If no, go to question 33.)
Material Loss: \$ 11,425.00
Carrier Damage: \$ 105,000.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 50,000.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality? False

If yes, enter the number of fatalities resulting from the hazardous material:
Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material? False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury? False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation? True

If yes, provide the following information:

Total number of general public evacuated: 16
Total number of employees evacuated:
Total evacuated: 16
Duration of the evacuation: 8

36. Was a major transportation artery or facility closed? False

If yes, how many?

37. Was the material involved in a crash or derailment? True

If yes, provide the following information:

Estimated speed (mph): 15
Weather conditions: CLESR
Vehicle overturned? True
Vehicle left roadway/track? True

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

A quarter mile from where the transport parks, heading east on Hemlock Rd our driver reached for a can of pop (soda). As the driver reached for the can of pop, he took his eyes off the road. When he looked back up his passenger side steer tire was in the shoulder (off the pavement). Driver tried to correct and get transport back onto the roadway. Driver overcorrected and rolled transport in the ditch. Compartment number one on the trailer hit a drainage culvert causing a release of ethanol. Compartment number one's manhole (15inches round) was opened when the trailer rolled over and slid backwards on the ground. Unknown the duration of the release. The Dodge County Sheriff and the Beaver Dam Fire Department responded to the accident site. The Beaver Dam Fire Department used floor dry to contain and absorb the spilled ethanol. They also used foam to prevent a spark. North Shore Environmental was called for spill response cleanup. Another Wayne Transports transport was sent to the site and the remaining ethanol was transferred into that trailer.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

Our driver was suspended from driving operations for one week, is placed on probation for one year, will be monitored via inward/outward facing cameras and audible warning system. Driver must also complete distracted driving training. Distracted driving was the root cause of the rollover accident and release of ethanol.

PART VIII – CONTACT INFORMATION

Contact's Name:	Ryan Vedders
Contact's Title:	Claims Manager
Business Name and Address:	WAYNE TRANSPORTS, INC. 14345 CONLEY AVE ROSEMOUNT MN 55068-4441
E-mail Address:	ryan@waynetransports.com
Telephone Number:	651-436-6495
Fax Number:	
Hazmat Registration Number:	041921550004DF
Date:	05/19/2022
Preparer is:	Carrier

06/25/2012