



U.S. Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: E-2014040526
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident:
04/21/2014
4. Time of Incident (use 24-hour time):
15:00
5. Enter National Response Center Report Number
(if applicable):
6. If you submitted a report to another Federal DOT agency, enter
the agency and report number:
7. Location of Incident:
- City: CLYDE
County: HAYWOOD
State: NC
Zip Code: (if known): 28721
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
MM 6 - I-40 W
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
- Name: WICKER SERVICES INC
Street: 2956 TUCKER ST
City: Burlington
State: NC
Zip Code: 27215
Federal DOT Id Number: 090899
Hazmat Registration Number: 051412701011UW
11. Shipper/Officer:
- Name: DYSTAR LP
Street: 209 WATLINGTON INDUSTRIAL DR
City: Reidsville
State: NC
Zip Code: 27320
Waybill/Shipping Paper: 100056306
Hazmat Registration Number: UNKNOWN
12. Origin (if different from shipper address)
- Street:
City:
State:
Zip Code:
13. Destination:
- Street: 2474 ABUTMENT ROAD
City: Dalton
State: GA
Zip Code: 30722
14. Proper Shipping Name of Hazardous Material: CHLORITE SOLUTION
15. Technical/Trade Name:
16. Hazardous Class/Division: Corrosive Material
17. Identification Number: (E.g. UN2764, NA 2020) UN1908

- 18. Packing Group:** (if applicable) III
- 19. Quantity Released:** (Include Measurement Units) 1375 Liquid - Gallon
- 20. Was the material shipped as a hazardous waste?** False
If yes, provide the EPA Manifest Number:
- 21. Is this a Toxic by Inhalation (TIH) material?** False
If yes, provide the Hazard Zone:
- 22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate?** False
If yes, provide the Exemption, Approval, or CA number:
- 23. Was this an undeclared hazardous materials shipment?** False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:
IBC

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: - 150-Tank Shell
How Failed: - 303-Burst or Ruptured
Causes of Failure: - Vehicular Crash or Accident Damage

26a. Provide the packaging identification markings, if available.

Identification Markings:

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Packaging Type: IBC Material of Construction: Plastic Head Type (Drums only):	Packaging Type: IBC Material of Construction: Plastic
27. Describe the package capacity and the quantity:	
Package Capacity: 275 Liquid - Gallon Amount in Package: 275 Liquid - Gallon Number in Shipment: 12 Number Failed: 5	Package Capacity: Amount in Package: Number in Shipment: Number Failed:
28. Provide packaging construction and test information, as appropriate:	
Manufacturer: UNKNOWN Serial Number: Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder) Design Pressure: (if Tank Car, CTMV, Portable Tank) Shell Thickness: (if Tank Car, CTMV, Portable Tank) Head Thickness: (if Tank Car, CTMV) Service Pressure: (if Cylinder) If valve or device failed: Type: Model: Manufacturer:	
29. If the packaging is for Radioactive Materials, complete the following:	
Packaging Category: Packaging Certification: Certification Number: Nuclide(s) Present: Transport Index: Activity: Critical Safety Index:	

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | False |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

Fire/EMS Report #: True 1400277
Police Report #: True UNKNOWN
In-house cleanup: False
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 50,000.00
Property Damage: \$ 0.00
Response Cost: \$ 4,680.00
Remediation/Cleanup Cost: \$ 25,000.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees: 0
Responders: 0
General Public: 0

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many? 0

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees: 0
Responders: 0
General Public: 0

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees: 0
Responders: 0
General Public: 0

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated: 0
Total number of employees evacuated: 0
Total evacuated: 0
Duration of the evacuation: 0

36. Was a major transportation artery or facility closed?

True

If yes, how many? 12

37. Was the material involved in a crash or derailment?

True

If yes, provide the following information:

Estimated speed (mph): 50
Weather conditions: clear
Vehicle overturned? True
Vehicle left roadway/track? False

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

TRACTOR TRAILER WESTBOUND ON I-40 NEAR MM6 ENTERED LEFT CURVE TOO FAST CAUSING LOAD TO SHIFT RIGHT AND OVERTURN VEHICLE. FIVE OF TWELVE IBC CONTAINERS (275 GALLON CAPACITY) RUPTURED ON IMPACT OF TURNOVER. EMERGENCY RESPONSE PERSONNEL FROM NORTH CAROLINA HIGHWAY PATROL AND JUNALUSKA FIRE DEPARTMENT RESPONDED AND CONTROLLED THE SCENE. HEPACO, CHARLOTTE, NC WAS CALLED TO HANDLE CLEANUP.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

THE 12 IBC CONTAINERS WERE LOADED WITH INADEQUATE SECUREMENT TO PREVENT SIDE SHIFTING. ANY FUTURE LOADS WILL BE SECURED TO NOT ALLOW SIDE SHIFTING OF CONTAINERS.

PART VIII – CONTACT INFORMATION

Contact's Name:	JIM WALKER
Contact's Title:	VP
Business Name and Address:	WICKER SERVICES , INC. 2956 TUCKER ST Burlington NC 27215
E-mail Address:	jwalker@wickerservices.com
Telephone Number:	336-227-1436
Fax Number:	336-570-3081
Hazmat Registration Number:	
Date:	04/24/2014
Preparer is:	Carrier