



U.S. Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: I-2003020526
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 06/04/2002
4. Time of Incident (use 24-hour time): 23:59
5. Enter National Response Center Report Number (if applicable):
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: SPRUCE PINE
County: MITCHELL
State: NC
Zip Code: (if known):
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
67 HIGHLAND AVENUE
8. Mode of Transportation: Highway
9. Transportation Phase: Unloading
10. Carrier/Reporter:
Name: CASON COMPANIES INC
Street: 1880 SPARTANBURG HIGHWAY
City: HENDERSONVILLE
State: NC
Zip Code: 28792
Federal DOT Id Number: 56-0863069
Hazmat Registration Number:
11. Shipper/Officer:
Name: CASON COMPANIES INC
Street: 1880 SPARTANBURG HIGHWAY
City: HENDERSONVILLE
State: NC
Zip Code: 28792
Waybill/Shipping Paper: 0230409
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street: 300 DELMAR ROAD
City: SPARTANBURG
State: SC
Zip Code:
13. Destination:
Street: 67 HIGHLAND AVENUE
City: SPRUCE PINE
State: NC
Zip Code: 28777
14. Proper Shipping Name of Hazardous Material: DIESEL FUEL
15. Technical/Trade Name:
16. Hazardous Class/Division: Flammable - Combustible Liquid
17. Identification Number: (E.g. UN2764, NA 2020) NA1993

18. Packing Group: (if applicable)

19. Quantity Released: (Include Measurement Units) 1000 Liquid - Gallon

20. Was the material shipped as a hazardous waste?

If yes, provide the EPA Manifest Number:

21. Is this a Toxic by Inhalation (TIH) material?

If yes, provide the Hazard Zone:

22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate?

If yes, provide the Exemption, Approval, or CA number:

23. Was this an undeclared hazardous materials shipment?

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:

Portable Tank

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: - 102-Auxiliary Valve; 109-Closure (e.g., Cap, Top, or Plug); 125-Hose; 135-Loading or Unloading Lines; 141-Piping or Fittings
How Failed: -
Causes of Failure: - Loose Closure, Component, or Device

26a. Provide the packaging identification markings, if available.

Identification Markings:

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Packaging Type:
Material of Construction:
Head Type (Drums only):

Packaging Type:
Material of Construction:

27. Describe the package capacity and the quantity:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Package Capacity: 8900 Liquid - Gallon
Amount in Package:
Number in Shipment: 1
Number Failed: 1

Package Capacity:
Amount in Package:
Number in Shipment:
Number Failed:

28. Provide packaging construction and test information, as appropriate:

Manufacturer: NOT REPORTED BY CARRIER
Serial Number: 1XPFD69XXT
Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder)
Design Pressure: (if Tank Car, CTMV, Portable Tank)
Shell Thickness: (if Tank Car, CTMV, Portable Tank)
Head Thickness: (if Tank Car, CTMV)
Service Pressure: (if Cylinder)

Manufacture Date:
Last Test Date:

If valve or device failed:

Type:
Model:
Manufacturer:

29. If the packaging is for Radioactive Materials, complete the following:

Packaging Category:
Packaging Certification:
Certification Number:
Nuclide(s) Present:
Activity:
Critical Safety Index:

Transport Index:

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | False |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | True |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

Fire/EMS Report #:
Police Report #:
In-house cleanup:
Other Cleanup:

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss:	\$ 1,167.00
Carrier Damage:	\$ 0.00
Property Damage:	\$ 0.00
Response Cost:	\$ 0.00
Remediation/Cleanup Cost:	\$ 10,080.00

(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees: 0
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

True

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees: 0
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees: 1
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

False

If yes, how many?

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

THE SPILL WAS CAUSED BY A LOOSE FITTING (THE RESULT OF CONSTRUCTION ON NEW PIPING). WHEN A TANKER TRUCK UNLOADED INTO THE NEW PIPING, THE LOOSE FITTING CAME APART, CREATING THE DISCHARGE OF 1,000 GALLONS OF DIESEL ONTO THE PROPERTY. THE PRODUCT LEAKED FROM THE LOADING RACK AREA TO THE OIL WATER SEPARATOR AREA AND LEFT THE PROPERTY AT THAT POINT; ENTERING THE TOE RIVER. THE DRIVER OF THE TANKER REALIZED WHAT WAS HAPPENING AND CEASED PUMPING AND ALERTED THE EMERGENCY MANAGEMENT TEAM. OF THE 1000 GALLONS, 400 WAS CONTAINED IN THE SPILL CONTAINMENT AREA AND APPROXIMATELY 422 GALLONS WAS DISCHARGED INTO THE NORTH TOE RIVER. THE BALANCE OF PRODUCT WAS CONTAINED IN THE SOIL ON THE PROPERTY WHICH WAS EVACUATED IMMEDIATELY AND REMOVED. THE CLEANUP CONTRACTOR (NEO) WAS NOTIFIED AND CONDUCTED ON-SITE CLEAN-UP BY USE OF BOOMS AND SORBANT IN THE RIVER. NEO FLOATED THE RIVER TO ENSURE THAT NO PRODUCT WAS LEFT ON THE BANKS OR IN THE WATER. FEDERAL AND STATE WILDLIFE AUTHORITIES MONITORED THE RIVER AS WELL. THE DURATION OF THE CLEAN-UP WAS TWO DAYS. ACTION TAKEN TO PREVENT FUTURE INCIDENTS: ADDITIONAL CONTAINMENT WALLS WERE BUILT, THE OLD LOADING RACK HAS BEEN DISCONTINUED, A NEW SPILL PLAN HAS BEEN WRITTEN AND STAFF HAS HAD REFRESHER TRAINING.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

PART VIII – CONTACT INFORMATION

Contact's Name: JOHN B GOULD
Contact's Title: PRESIDENT
Business Name and Address:

E-mail Address:
Telephone Number: 828-693-0246
Fax Number:
Hazmat Registration Number:
Date: 02/05/2003
Preparer is: