



U.S. Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: I-2011040233
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident:
03/07/2011
4. Time of Incident (use 24-hour time):
04:30
5. Enter National Response Center Report Number (if applicable):
969460
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: TEXARKANA
County: BOWIE
State: TX
Zip Code: (if known):
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
RANDEL RD & HWY 59
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: STAR TRANSPORTATION LLC
Street: 3201 EAST HIGHLAND DRIVE
City: Jonesboro
State: AR
Zip Code: 72401
Federal DOT Id Number: 564721
Hazmat Registration Number: 062210552049SU
11. Shipper/Officer:
Name: EXXON MOBIL CORPORATION
Street: 3225 GALLOWS ROAD
City: FAIRFAX
State: VA
Zip Code: 22037-0001
Waybill/Shipping Paper: 0058477
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City: WASKOM
State: TX
Zip Code: 75692
13. Destination:
Street: 1100 ELYSIAN FIELDS RD
City: TEXARKANA
State: TX
Zip Code:
14. Proper Shipping Name of Hazardous Material: GASOHOL GASOLINE MIXED WITH ETHYL ALCOHOL, WITH NOT MORE THAN 10% ALCOHOL
15. Technical/Trade Name: 87 R9 & REG E10
16. Hazardous Class/Division: Flammable - Combustible Liquid
17. Identification Number: (E.g. UN2764, NA 2020) NA1203

18. Packing Group: (if applicable)

19. Quantity Released: (Include Measurement Units) 250 Liquid - Gallon

20. Was the material shipped as a hazardous waste? False

If yes, provide the EPA Manifest Number:

21. Is this a Toxic by Inhalation (TIH) material? False

If yes, provide the Hazard Zone:

22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate? False

If yes, provide the Exemption, Approval, or CA number:

23. Was this an undeclared hazardous materials shipment? False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:

Cargo Tank Motor Vehicle (CTMV)

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: - 150-Tank Shell

How Failed: - 302-Bent

Causes of Failure: - Vehicular Crash or Accident Damage

26a. Provide the packaging identification markings, if available.

Identification Markings: NO MARKINGS PROVIDED

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Packaging Type:
Material of Construction:
Head Type (Drums only):

Packaging Type:
Material of Construction:

27. Describe the package capacity and the quantity:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Package Capacity:
Amount in Package:
Number in Shipment:
Number Failed:

Package Capacity:
Amount in Package:
Number in Shipment:
Number Failed:

28. Provide packaging construction and test information, as appropriate:

Manufacturer:	HEL TRAILER INTERNATIONAL	Manufacture Date:	01/01/2006
Serial Number:	5HTAB432067H7174	Last Test Date:	03/01/2011
Material of Construction:	ALUMINUM (if Tank Car, CTMV, Portable Tank, or Cylinder)		
Design Pressure:	3 (if Tank Car, CTMV, Portable Tank)		
Shell Thickness:	0.204 INCH (if Tank Car, CTMV, Portable Tank)		
Head Thickness:	0.176 INCH (if Tank Car, CTMV)		
Service Pressure:	(if Cylinder)		
If valve or device failed:			
Type:			
Model:			
Manufacturer:			

29. If the packaging is for Radioactive Materials, complete the following:

Packaging Category:	
Packaging Certification:	
Certification Number:	
Nuclide(s) Present:	Transport Index:
Activity:	
Critical Safety Index:	

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | False |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | True |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

Fire/EMS Report #: True 3-18-11
Police Report #: True TXDPS3100
In-house cleanup: False
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 2,600.00
Carrier Damage: \$ 115,000.00
Property Damage: \$ 0.00
Response Cost: \$ 16,167.00
Remediation/Cleanup Cost: \$ 40,000.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees: 0
Responders: 0
General Public: 0

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many? 0

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees: 0
Responders: 0
General Public: 0

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees: 0
Responders: 0
General Public: 0

35. Did the hazardous material cause or contribute to an evacuation?

True

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated:
Duration of the evacuation: 6

36. Was a major transportation artery or facility closed?

True

If yes, how many? 6

37. Was the material involved in a crash or derailment?

True

If yes, provide the following information:

Estimated speed (mph): 55
Weather conditions: DARK, CLOUDY
Vehicle overturned? False
Vehicle left roadway/track? True

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

BLACK SUV CROSSED LINE CAUSING OUR TRUCK TO MOVE TO THE RIGHT SHOULDER. THE LOOSE SHOULDER ALLOWED OUR TRUCK AND TANKER TO LEAVE THE ROAD AND ENTER TREE LINE AREA ACROSS THE ROAD FROM A SCHOOL. HITTING TREES ALLOWED A FOLDED PIECE ON FRONT COMPARTMENT TO LEAK AT A VERY SLOW RATE UNTIL THE VAC TRUCK COULD EMPTY IT. ESTIMATED AT 250 GALLONS. SPILL WAS ONTO DIRT IN LOWER AREA WITH NO ACCESS TO WATER OR DRAINS. MICRO BLAZE AND FOAM CONTAINED FUMES. TAS ENVIRONMENTAL WAS ON THE SCENE AS FIRE DEPT ARRIVE. HWY 59 WAS CLOSED FOR ABOUT 6 HOURS.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

DRIVER REACTED AS EXPECTED TO AVOID ONCOMING VEHICLE. IF SHOULDER WAS WIDER OR CURBED, HE MAY HAVE MAINTAINED HIS POSITION. ANIT-ROLLOVER SYSTEM HELPED KEEP TANKER UPRIGHT, OFF ROAD.

PART VIII – CONTACT INFORMATION

Contact's Name:	RANDALL STATLER
Contact's Title:	SAFETY COORDINATOR
Business Name and Address:	STAR TRANSPORTATION 3201 E HIGHLAND DR JONESBORO AR 72401
E-mail Address:	RANDY.STATLER@STARTRANSPORTATIONLLC.COM
Telephone Number:	870-930-6962
Fax Number:	870-932-2925
Hazmat Registration Number:	062210552049SU
Date:	03/25/2011
Preparer is:	Carrier

01/01/2006