



U.S. Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: E-2026070099
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident:
07/02/2026
4. Time of Incident (use 24-hour time):
20:09
5. Enter National Response Center Report Number (if applicable):
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
- City: CEDAR RAPIDS
County: LINN
State: IA
Zip Code: (if known): 52404
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
651 50th Ave Dr SW
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
- Name: XPO ENTERPRISE SERVICES, INC.
Street: 2211 OLD EARHART RD STE 100
City: ANN ARBOR
State: MI
Zip Code: 48105-2963
Federal DOT Id Number: 838885
Hazmat Registration Number:
11. Shipper/Officer:
- Name: HYDRITE CHEMICAL CO.
Street: 2815 WCF AND N DR
City: WATERLOO
State: IA
Zip Code: 50703-9612
Waybill/Shipping Paper: Hazmat Registration Number:
12. Origin (if different from shipper address)
- Street:
City:
State:
Zip Code:
13. Destination:
- Street: 22123 Hwy 5
City: MILAN
State: MO
Zip Code: 63556
14. Proper Shipping Name of Hazardous Material: SODIUM HYDROXIDE, SOLUTION
15. Technical/Trade Name: Caus Soda Liq 50%
16. Hazardous Class/Division: Corrosive Material
17. Identification Number: (E.g. UN2764, NA 2020) UN1824

- 18. Packing Group:** (if applicable) II
- 19. Quantity Released:** (Include Measurement Units) 130 Liquid - Gallon
- 20. Was the material shipped as a hazardous waste?** False
If yes, provide the EPA Manifest Number:
- 21. Is this a Toxic by Inhalation (TIH) material?** False
If yes, provide the Hazard Zone:
- 22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate?** False
If yes, provide the Exemption, Approval, or CA number:
- 23. Was this an undeclared hazardous materials shipment?** False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:
IBC

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: - 104-Body

How Failed: - 309-Punctured

Causes of Failure: - Impact with Sharp or Protruding Object (e.g., nails)

26a. Provide the packaging identification markings, if available.

Identification Markings:

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Packaging Type: IBC Material of Construction: Plastic Head Type (Drums only):	Packaging Type: Material of Construction:
27. Describe the package capacity and the quantity:	
Package Capacity: 330 Liquid - Gallon Amount in Package: 330 Liquid - Gallon Number in Shipment: 2 Number Failed: 1	Package Capacity: Amount in Package: Number in Shipment: Number Failed:
28. Provide packaging construction and test information, as appropriate: Manufacturer: Serial Number: Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder) Design Pressure: (if Tank Car, CTMV, Portable Tank) Shell Thickness: (if Tank Car, CTMV, Portable Tank) Head Thickness: (if Tank Car, CTMV) Service Pressure: (if Cylinder) If valve or device failed: Type: Model: Manufacturer:	
29. If the packaging is for Radioactive Materials, complete the following: Packaging Category: Packaging Certification: Certification Number: Nuclide(s) Present: Transport Index: Activity: Critical Safety Index:	

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|--|
| - Spillage: | True | - Fire: | |
| - Explosion: | | - Material Entered Waterway/Storm Sewer: | |
| - Vapor (Gas) Dispersion: | | - Environmental Damage: | |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

Fire/EMS Report #: _____
Police Report #: _____
In-house cleanup: _____
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss:	\$ 0.00
Carrier Damage:	\$ 0.00
Property Damage:	\$ 0.00
Response Cost:	\$ 10,000.00
Remediation/Cleanup Cost:	\$ 0.00

(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees: _____
Responders: _____
General Public: _____

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees: _____
Responders: _____
General Public: _____

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees: _____
Responders: _____
General Public: _____

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated: _____
Total number of employees evacuated: _____
Total evacuated: 0
Duration of the evacuation: _____

36. Was a major transportation artery or facility closed?

False

If yes, how many?

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph): _____
Weather conditions: _____
Vehicle overturned? _____
Vehicle left roadway/track? _____

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

At 2019ET XPO reported a spill of Caus Soda Liq 50% FG from one 330-gallon IBC tote releasing 165 gallons onto the trailer floor, concrete dock and below the trailer due to improper loading. The terminal has used floor dri to keep the spill contained but was instructed by the EOC to stay away from the spill and block off the trailer until the crew has arrived to clean the spill.

Contractors arrived onsite and confirmed approximately 130-gallons of UN1824 Caus Soda Liq 50% released impacting entire trailer floor, loading dock and 10'x70' underneath trailer due to improper loading. The team transferred the remaining product into a new poly tote and cut up the damaged tote. The damaged tote was containerized into a 55-gallon poly tote. The absorbents, PPE and debris were containerized into (6) 55-gallon poly drums. The waste was staged onsite for terminal personnel to manage

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

No comments provided.

PART VIII – CONTACT INFORMATION

Contact's Name:	Gloria Brown
Contact's Title:	NA
Business Name and Address:	ERTS 11231 Phillips Industrial Blvd Ste 300 Jacksonville FL
E-mail Address:	brown.gloria@cleanharbors.com
Telephone Number:	(904)874-8825
Fax Number:	
Hazmat Registration Number:	
Date:	07/06/2026
Preparer is:	Other - Agent for Carrier