



U.S. Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: E-2021040274
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident:
04/12/2021
4. Time of Incident (use 24-hour time):
08:30
5. Enter National Response Center Report Number (if applicable):
1302507
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: GAINESVILLE
County: COOKE
State: TX
Zip Code: (if known): 76240
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
I-35 NB past exit 494
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: COMPOSITES ONE LLC
Street: 85 W ALGONQUIN RD STE 600
City: ARLINGTON HEIGHTS
State: IL
Zip Code: 60005-4421
Federal DOT Id Number:
Hazmat Registration Number:
11. Shipper/Offeror:
Name: Composites One LLC
Street: 905 Railhead Drive
City: Fort Worth
State: TX
Zip Code: 76177
Waybill/Shipping Paper: 27316930
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: 1711 Westair
City: GAINESVILLE
State: TX
Zip Code: 76240
14. Proper Shipping Name of Hazardous Material: RESIN SOLUTION, FLAMMABLE
15. Technical/Trade Name: FV945-YA-058 Orange Tooling Gel
16. Hazardous Class/Division: Flammable - Combustible Liquid

17. Identification Number: (E.g. UN2764, NA 2020) UN1866

18. Packing Group: (if applicable) III

19. Quantity Released: (Include Measurement Units) 45 Liquid - Pound

20. Was the material shipped as a hazardous waste? False
If yes, provide the EPA Manifest Number:

21. Is this a Toxic by Inhalation (TIH) material? False
If yes, provide the Hazard Zone:

22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate? False
If yes, provide the Exemption, Approval, or CA number:

23. Was this an undeclared hazardous materials shipment? False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:
Non-Bulk

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.
Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: - 104-Body
How Failed: - 313-Vented
Causes of Failure: - Vehicular Crash or Accident Damage

26a. Provide the packaging identification markings, if available.

Identification Markings: 1A

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Packaging Type: Drum Material of Construction: Steel Head Type (Drums only): Non - Removable	Packaging Type: Material of Construction:

27. Describe the package capacity and the quantity:

Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Package Capacity: 45 Liquid - Pound Amount in Package: 45 Liquid - Pound Number in Shipment: 1 Number Failed: 1	Package Capacity: Amount in Package: Number in Shipment: Number Failed:

28. Provide packaging construction and test information, as appropriate:

Manufacturer:	Manufacture Date:
Serial Number:	Last Test Date:
Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder)	
Design Pressure: (if Tank Car, CTMV, Portable Tank)	
Shell Thickness: (if Tank Car, CTMV, Portable Tank)	
Head Thickness: (if Tank Car, CTMV)	
Service Pressure: (if Cylinder)	
If valve or device failed:	
Type:	
Model:	
Manufacturer:	

29. If the packaging is for Radioactive Materials, complete the following:

Packaging Category:	
Packaging Certification:	
Certification Number:	
Nuclide(s) Present:	Transport Index:
Activity:	
Critical Safety Index:	

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | True |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

- Fire/EMS Report #: True
Police Report #: True
In-house cleanup: False
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 23,500.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

True

If yes, how many? 10

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

ERTS was contacted by Composites One - regarding a truck (#2256) fire that occurred on I-35 NB past exit 494 - in Gainesville, TX due to a mechanical failure when the brakes locked up. The caller has requested a contractor out for cleanup and containment of the waste and debris that has impacted asphalt, soil, and grass. The caller advise the fire dept. is on site and has put out the fire. The trailer is completely destroyed. The roads around the incident have been closed off by police who are also on site.

ERTS dispatched an environmental contractor who confirmed the released was contained to the asphalt roadway and soul median. The contractor excavated the impacted area of soil and clean the impacted roadway. All waste was collected, containerized and taken off site for pending disposal.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

NO COMMENTS PROVIDED.

PART VIII – CONTACT INFORMATION

Contact's Name:	Keith Witkowski
Contact's Title:	PM
Business Name and Address:	EMERGENCY RESPONSE AND TRAININGSOLUTIONS 6001 COCHRAN RD STE 300 SOLON OH 44139-3302
E-mail Address:	kwitkowski@ertsonline.com
Telephone Number:	(440)349-2700
Fax Number:	(440)349-2700
Hazmat Registration Number:	
Date:	04/15/2021
Preparer is:	Other - agent for RP



U.S Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: E-2021040274
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/12/2021
4. Time of Incident (use 24-hour time): 08:30
5. Enter National Response Center Report Number (if applicable): 1302507
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: GAINESVILLE
County: COOKE
State: TX
Zip Code: (if known): 76240
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
I-35 NB past exit 494
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: COMPOSITES ONE LLC
Street: 85 W ALGONQUIN RD STE 600
City: ARLINGTON HEIGHTS
State: IL
Zip Code: 60005-4421
Federal DOT Id Number: Hazmat Registration Number:
11. Shipper/Offeror:
Name: Composites One LLC
Street: 905 Railhead Drive
City: Fort Worth
State: TX
Zip Code: 76177
Waybill/Shipping Paper: 27316930
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: 1711 Westair
City: GAINESVILLE
State: TX
Zip Code: 76240
14. Proper Shipping Name of Hazardous Material: RESIN SOLUTION, FLAMMABLE
15. Technical/Trade Name: LHPC-2700 Laminating Resin
16. Hazardous Class/Division: Flammable - Combustible Liquid
17. Identification Number: (E.g. UN2764, NA 2020) UN1866

18. Packing Group: (if applicable) III

19. Quantity Released: (Include Measurement Units) 4600 Liquid - Pound

20. Was the material shipped as a hazardous waste? False
If yes, provide the EPA Manifest Number:

21. Is this a Toxic by Inhalation (TIH) material? False
If yes, provide the Hazard Zone:

22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate? False
If yes, provide the Exemption, Approval, or CA number:

23. Was this an undeclared hazardous materials shipment? False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:
IBC

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.
Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: - 104-Body
How Failed: - 303-Burst or Ruptured
Causes of Failure: - Vehicular Crash or Accident Damage

26a. Provide the packaging identification markings, if available.

Identification Markings: 1

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Packaging Type: IBC Material of Construction: Metal Head Type (Drums only):	Packaging Type: Material of Construction:

27. Describe the package capacity and the quantity:

Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Package Capacity: 4600 Liquid - Pound Amount in Package: 4600 Liquid - Pound Number in Shipment: 1 Number Failed: 1	Package Capacity: Amount in Package: Number in Shipment: Number Failed:

28. Provide packaging construction and test information, as appropriate:

Manufacturer:	Manufacture Date:
Serial Number:	Last Test Date:
Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder)	
Design Pressure: (if Tank Car, CTMV, Portable Tank)	
Shell Thickness: (if Tank Car, CTMV, Portable Tank)	
Head Thickness: (if Tank Car, CTMV)	
Service Pressure: (if Cylinder)	
If valve or device failed:	
Type:	
Model:	
Manufacturer:	

29. If the packaging is for Radioactive Materials, complete the following:

Packaging Category:	
Packaging Certification:	
Certification Number:	
Nuclide(s) Present:	Transport Index:
Activity:	
Critical Safety Index:	

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | True |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

- Fire/EMS Report #: True
Police Report #: True
In-house cleanup: False
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 23,500.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

True

If yes, how many? 10

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

ERTS was contacted by Composites One - regarding a truck (#2256) fire that occurred on I-35 NB past exit 494 - in Gainesville, TX due to a mechanical failure when the brakes locked up. The caller has requested a contractor out for cleanup and containment of the waste and debris that has impacted asphalt, soil, and grass. The caller advise the fire dept. is on site and has put out the fire. The trailer is completely destroyed. The roads around the incident have been closed off by police who are also on site.

ERTS dispatched an environmental contractor who confirmed the released was contained to the asphalt roadway and soul median. The contractor excavated the impacted area of soil and clean the impacted roadway. All waste was collected, containerized and taken off site for pending disposal.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

NO COMMENTS PROVIDED.

PART VIII – CONTACT INFORMATION

Contact's Name:	Keith Witkowski
Contact's Title:	PM
Business Name and Address:	EMERGENCY RESPONSE AND TRAININGSOLUTIONS 6001 COCHRAN RD STE 300 SOLON OH 44139-3302
E-mail Address:	kwitkowski@ertsonline.com
Telephone Number:	(440)349-2700
Fax Number:	(440)349-2700
Hazmat Registration Number:	
Date:	04/15/2021
Preparer is:	Other - agent for RP



U.S Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: E-2021040274
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/12/2021
4. Time of Incident (use 24-hour time): 08:30
5. Enter National Response Center Report Number (if applicable): 1302507
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: GAINESVILLE
County: COOKE
State: TX
Zip Code: (if known): 76240
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
I-35 NB past exit 494
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: COMPOSITES ONE LLC
Street: 85 W ALGONQUIN RD STE 600
City: ARLINGTON HEIGHTS
State: IL
Zip Code: 60005-4421
Federal DOT Id Number:
Hazmat Registration Number:
11. Shipper/Offeror:
Name: Composites One LLC
Street: 905 Railhead Drive
City: Fort Worth
State: TX
Zip Code: 76177
Waybill/Shipping Paper: 27316930
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: 1711 Westair
City: Gainesville
State: TX
Zip Code: 76240
14. Proper Shipping Name of Hazardous Material: ORGANIC PEROXIDE TYPE D, LIQUID
15. Technical/Trade Name: Luperox DDM9
16. Hazardous Class/Division: Organic Peroxide
17. Identification Number: (E.g. UN2764, NA 2020) UN3105

18. Packing Group: (if applicable)

19. Quantity Released: (Include Measurement Units) 64 Liquid - Pound

20. Was the material shipped as a hazardous waste? False

If yes, provide the EPA Manifest Number:

21. Is this a Toxic by Inhalation (TIH) material? False

If yes, provide the Hazard Zone:

22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate? False

If yes, provide the Exemption, Approval, or CA number:

23. Was this an undeclared hazardous materials shipment? False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:

Non-Bulk

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: - 104-Body

How Failed: - 303-Burst or Ruptured

Causes of Failure: - Vehicular Crash or Accident Damage

26a. Provide the packaging identification markings, if available.

Identification Markings: 4G

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Packaging Type: Box Material of Construction: Fiberboard Head Type (Drums only):	Packaging Type: Bottle Material of Construction: Plastic
27. Describe the package capacity and the quantity:	
Package Capacity: 64 Liquid - Pound Amount in Package: 64 Liquid - Pound Number in Shipment: 1 Number Failed: 1	Package Capacity: Amount in Package: Number in Shipment: Number Failed:
28. Provide packaging construction and test information, as appropriate: Manufacturer: Serial Number: Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder) Design Pressure: (if Tank Car, CTMV, Portable Tank) Shell Thickness: (if Tank Car, CTMV, Portable Tank) Head Thickness: (if Tank Car, CTMV) Service Pressure: (if Cylinder) If valve or device failed: Type: Model: Manufacturer:	
29. If the packaging is for Radioactive Materials, complete the following: Packaging Category: Packaging Certification: Certification Number: Nuclide(s) Present: Transport Index: Activity: Critical Safety Index:	

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | True |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

- Fire/EMS Report #: True
Police Report #: True
In-house cleanup: False
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 23,500.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

True

If yes, how many? 10

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

ERTS was contacted by Composites One - regarding a truck (#2256) fire that occurred on I-35 NB past exit 494 - in Gainesville, TX due to a mechanical failure when the brakes locked up. The caller has requested a contractor out for cleanup and containment of the waste and debris that has impacted asphalt, soil, and grass. The caller advise the fire dept. is on site and has put out the fire. The trailer is completely destroyed. The roads around the incident have been closed off by police who are also on site.

ERTS dispatched an environmental contractor who confirmed the released was contained to the asphalt roadway and soul median. The contractor excavated the impacted area of soil and clean the impacted roadway. All waste was collected, containerized and taken off site for pending disposal.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

NO COMMENTS PROVIDED.

PART VIII – CONTACT INFORMATION

Contact's Name:	Keith Witkowski
Contact's Title:	PM
Business Name and Address:	EMERGENCY RESPONSE AND TRAININGSOLUTIONS 6001 COCHRAN RD STE 300 SOLON OH 44139-3302
E-mail Address:	kwitkowski@ertsonline.com
Telephone Number:	(440)349-2700
Fax Number:	(440)349-2700
Hazmat Registration Number:	
Date:	04/15/2021
Preparer is:	Other - agent for RP



U.S Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: E-2021040274
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/12/2021
4. Time of Incident (use 24-hour time): 08:30
5. Enter National Response Center Report Number (if applicable): 1302507
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: GAINESVILLE
County: COOKE
State: TX
Zip Code: (if known): 76240
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
I-35 NB past exit 494
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: COMPOSITES ONE LLC
Street: 85 W ALGONQUIN RD STE 600
City: ARLINGTON HEIGHTS
State: IL
Zip Code: 60005-4421
Federal DOT Id Number: Hazmat Registration Number:
11. Shipper/Offeror:
Name: Composites One LLC
Street: 905 Railhead Drive
City: Fort Worth
State: TX
Zip Code: 76177
Waybill/Shipping Paper: 27316930
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: 1711 Westair
City: GAINESVILLE
State: TX
Zip Code: 76240
14. Proper Shipping Name of Hazardous Material: RESIN SOLUTION, FLAMMABLE
15. Technical/Trade Name: RTM Resin
16. Hazardous Class/Division: Flammable - Combustible Liquid
17. Identification Number: (E.g. UN2764, NA 2020) UN1866

- 18. Packing Group:** (if applicable) III
- 19. Quantity Released:** (Include Measurement Units) 2000 Liquid - Pound
- 20. Was the material shipped as a hazardous waste?** False
If yes, provide the EPA Manifest Number:
- 21. Is this a Toxic by Inhalation (TIH) material?** False
If yes, provide the Hazard Zone:
- 22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate?** False
If yes, provide the Exemption, Approval, or CA number:
- 23. Was this an undeclared hazardous materials shipment?** False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:
Non-Bulk

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: - 104-Body
How Failed: - 303-Burst or Ruptured
Causes of Failure: - Vehicular Crash or Accident Damage

26a. Provide the packaging identification markings, if available.

Identification Markings: 1A

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Packaging Type: Drum Material of Construction: Steel Head Type (Drums only): Non - Removable	Packaging Type: Material of Construction:

27. Describe the package capacity and the quantity:

Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Package Capacity: 2000 Liquid - Pound Amount in Package: 2000 Liquid - Pound Number in Shipment: 1 Number Failed: 1	Package Capacity: Amount in Package: Number in Shipment: Number Failed:

28. Provide packaging construction and test information, as appropriate:

Manufacturer:	Manufacture Date:
Serial Number:	Last Test Date:
Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder)	
Design Pressure: (if Tank Car, CTMV, Portable Tank)	
Shell Thickness: (if Tank Car, CTMV, Portable Tank)	
Head Thickness: (if Tank Car, CTMV)	
Service Pressure: (if Cylinder)	
If valve or device failed:	
Type:	
Model:	
Manufacturer:	

29. If the packaging is for Radioactive Materials, complete the following:

Packaging Category:	
Packaging Certification:	
Certification Number:	
Nuclide(s) Present:	Transport Index:
Activity:	
Critical Safety Index:	

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | True |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

- Fire/EMS Report #: True
Police Report #: True
In-house cleanup: False
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 23,500.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

True

If yes, how many? 10

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

ERTS was contacted by Composites One - regarding a truck (#2256) fire that occurred on I-35 NB past exit 494 - in Gainesville, TX due to a mechanical failure when the brakes locked up. The caller has requested a contractor out for cleanup and containment of the waste and debris that has impacted asphalt, soil, and grass. The caller advise the fire dept. is on site and has put out the fire. The trailer is completely destroyed. The roads around the incident have been closed off by police who are also on site.

ERTS dispatched an environmental contractor who confirmed the released was contained to the asphalt roadway and soul median. The contractor excavated the impacted area of soil and clean the impacted roadway. All waste was collected, containerized and taken off site for pending disposal.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

NO COMMENTS PROVIDED.

PART VIII – CONTACT INFORMATION

Contact's Name:	Keith Witkowski
Contact's Title:	PM
Business Name and Address:	EMERGENCY RESPONSE AND TRAININGSOLUTIONS 6001 COCHRAN RD STE 300 SOLON OH 44139-3302
E-mail Address:	kwitkowski@ertsonline.com
Telephone Number:	(440)349-2700
Fax Number:	(440)349-2700
Hazmat Registration Number:	
Date:	04/15/2021
Preparer is:	Other - agent for RP



U.S Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: E-2021040274
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/12/2021
4. Time of Incident (use 24-hour time): 08:30
5. Enter National Response Center Report Number (if applicable): 1302507
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: GAINESVILLE
County: COOKE
State: TX
Zip Code: (if known): 76240
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
I-35 NB past exit 494
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: COMPOSITES ONE LLC
Street: 85 W ALGONQUIN RD STE 600
City: ARLINGTON HEIGHTS
State: IL
Zip Code: 60005-4421
Federal DOT Id Number: Hazmat Registration Number:
11. Shipper/Offeror:
Name: Composites One LLC
Street: 905 Railhead Drive
City: Fort Worth
State: TX
Zip Code: 76177
Waybill/Shipping Paper: 27316930
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: 1700 Westair Dr
City: GAINESVILLE
State: TX
Zip Code: 76240
14. Proper Shipping Name of Hazardous Material: RESIN SOLUTION, FLAMMABLE
15. Technical/Trade Name: LHPC2700 Resin
16. Hazardous Class/Division: Flammable - Combustible Liquid
17. Identification Number: (E.g. UN2764, NA 2020) UN1866

- 18. Packing Group:** (if applicable) III
- 19. Quantity Released:** (Include Measurement Units) 1000 Liquid - Pound
- 20. Was the material shipped as a hazardous waste?** False
If yes, provide the EPA Manifest Number:
- 21. Is this a Toxic by Inhalation (TIH) material?** False
If yes, provide the Hazard Zone:
- 22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate?** False
If yes, provide the Exemption, Approval, or CA number:
- 23. Was this an undeclared hazardous materials shipment?** False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:
Non-Bulk

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: - 104-Body
How Failed: - 303-Burst or Ruptured
Causes of Failure: - Vehicular Crash or Accident Damage

26a. Provide the packaging identification markings, if available.

Identification Markings: 1A

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Packaging Type: Drum Material of Construction: Steel Head Type (Drums only): Non - Removable	Packaging Type: Material of Construction:

27. Describe the package capacity and the quantity:

Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Package Capacity: 1000 Liquid - Pound Amount in Package: 1000 Liquid - Pound Number in Shipment: 1 Number Failed: 1	Package Capacity: Amount in Package: Number in Shipment: Number Failed:

28. Provide packaging construction and test information, as appropriate:

Manufacturer:	Manufacture Date:
Serial Number:	Last Test Date:
Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder)	
Design Pressure: (if Tank Car, CTMV, Portable Tank)	
Shell Thickness: (if Tank Car, CTMV, Portable Tank)	
Head Thickness: (if Tank Car, CTMV)	
Service Pressure: (if Cylinder)	
If valve or device failed:	
Type:	
Model:	
Manufacturer:	

29. If the packaging is for Radioactive Materials, complete the following:

Packaging Category:	
Packaging Certification:	
Certification Number:	
Nuclide(s) Present:	Transport Index:
Activity:	
Critical Safety Index:	

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | True |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

- Fire/EMS Report #: True
Police Report #: True
In-house cleanup: False
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 23,500.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

True

If yes, how many? 10

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

ERTS was contacted by Composites One - regarding a truck (#2256) fire that occurred on I-35 NB past exit 494 - in Gainesville, TX due to a mechanical failure when the brakes locked up. The caller has requested a contractor out for cleanup and containment of the waste and debris that has impacted asphalt, soil, and grass. The caller advise the fire dept. is on site and has put out the fire. The trailer is completely destroyed. The roads around the incident have been closed off by police who are also on site.

ERTS dispatched an environmental contractor who confirmed the released was contained to the asphalt roadway and soul median. The contractor excavated the impacted area of soil and clean the impacted roadway. All waste was collected, containerized and taken off site for pending disposal.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

NO COMMENTS PROVIDED.

PART VIII - CONTACT INFORMATION

Contact's Name:	Keith Witkowski
Contact's Title:	PM
Business Name and Address:	EMERGENCY RESPONSE AND TRAININGSOLUTIONS 6001 COCHRAN RD STE 300 SOLON OH 44139-3302
E-mail Address:	kwitkowski@ertsonline.com
Telephone Number:	(440)349-2700
Fax Number:	(440)349-2700
Hazmat Registration Number:	
Date:	04/15/2021
Preparer is:	Other - agent for RP



U.S Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: E-2021040274
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/12/2021
4. Time of Incident (use 24-hour time): 08:30
5. Enter National Response Center Report Number (if applicable): 1302507
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: GAINESVILLE
County: COOKE
State: TX
Zip Code: (if known): 76240
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
I-35 NB past exit 494
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: COMPOSITES ONE LLC
Street: 85 W ALGONQUIN RD STE 600
City: ARLINGTON HEIGHTS
State: IL
Zip Code: 60005-4421
Federal DOT Id Number: Hazmat Registration Number:
11. Shipper/Offeror:
Name: Composites One LLC
Street: 905 Railhead Drive
City: Fort Worth
State: TX
Zip Code: 76177
Waybill/Shipping Paper: 27316930
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: 1700 Westair
City: GAINESVILLE
State: TX
Zip Code: 76240
14. Proper Shipping Name of Hazardous Material: RESIN SOLUTION, FLAMMABLE
15. Technical/Trade Name: Sanding Primer
16. Hazardous Class/Division: Flammable - Combustible Liquid
17. Identification Number: (E.g. UN2764, NA 2020) UN1866

18. Packing Group: (if applicable)

19. Quantity Released: (Include Measurement Units) 40 Liquid - Pound

20. Was the material shipped as a hazardous waste? False

If yes, provide the EPA Manifest Number:

21. Is this a Toxic by Inhalation (TIH) material? False

If yes, provide the Hazard Zone:

22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate? False

If yes, provide the Exemption, Approval, or CA number:

23. Was this an undeclared hazardous materials shipment? False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:

Non-Bulk

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: - 104-Body

How Failed: - 303-Burst or Ruptured

Causes of Failure: - Vehicular Crash or Accident Damage

26a. Provide the packaging identification markings, if available.

Identification Markings: 4G

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Packaging Type: Box Material of Construction: Fiberboard Head Type (Drums only):	Packaging Type: Bottle Material of Construction: Metal (any type)
27. Describe the package capacity and the quantity:	
Package Capacity: 40 Liquid - Pound Amount in Package: 40 Liquid - Pound Number in Shipment: 1 Number Failed: 1	Package Capacity: Amount in Package: Number in Shipment: Number Failed:
28. Provide packaging construction and test information, as appropriate: Manufacturer: Serial Number: Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder) Design Pressure: (if Tank Car, CTMV, Portable Tank) Shell Thickness: (if Tank Car, CTMV, Portable Tank) Head Thickness: (if Tank Car, CTMV) Service Pressure: (if Cylinder) If valve or device failed: Type: Model: Manufacturer:	
29. If the packaging is for Radioactive Materials, complete the following: Packaging Category: Packaging Certification: Certification Number: Nuclide(s) Present: Transport Index: Activity: Critical Safety Index:	

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | True |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

- Fire/EMS Report #: True
Police Report #: True
In-house cleanup: False
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 23,500.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

True

If yes, how many? 10

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

ERTS was contacted by Composites One - regarding a truck (#2256) fire that occurred on I-35 NB past exit 494 - in Gainesville, TX due to a mechanical failure when the brakes locked up. The caller has requested a contractor out for cleanup and containment of the waste and debris that has impacted asphalt, soil, and grass. The caller advise the fire dept. is on site and has put out the fire. The trailer is completely destroyed. The roads around the incident have been closed off by police who are also on site.

ERTS dispatched an environmental contractor who confirmed the released was contained to the asphalt roadway and soul median. The contractor excavated the impacted area of soil and clean the impacted roadway. All waste was collected, containerized and taken off site for pending disposal.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

NO COMMENTS PROVIDED.

PART VIII - CONTACT INFORMATION

Contact's Name:	Keith Witkowski
Contact's Title:	PM
Business Name and Address:	EMERGENCY RESPONSE AND TRAININGSOLUTIONS 6001 COCHRAN RD STE 300 SOLON OH 44139-3302
E-mail Address:	kwitkowski@ertsonline.com
Telephone Number:	(440)349-2700
Fax Number:	(440)349-2700
Hazmat Registration Number:	
Date:	04/15/2021
Preparer is:	Other - agent for RP



U.S Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: E-2021040274
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/12/2021
4. Time of Incident (use 24-hour time): 08:30
5. Enter National Response Center Report Number (if applicable): 1302507
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: GAINESVILLE
County: COOKE
State: TX
Zip Code: (if known): 76240
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
I-35 NB past exit 494
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: COMPOSITES ONE LLC
Street: 85 W ALGONQUIN RD STE 600
City: ARLINGTON HEIGHTS
State: IL
Zip Code: 60005-4421
Federal DOT Id Number: Hazmat Registration Number:
11. Shipper/Offeror:
Name: Composites One LLC
Street: 905 Railhead Drive
City: Fort Worth
State: TX
Zip Code: 76177
Waybill/Shipping Paper: 27316930
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: 1700 Westair
City: GAINESVILLE
State: TX
Zip Code: 76240
14. Proper Shipping Name of Hazardous Material: RESIN SOLUTION, FLAMMABLE
15. Technical/Trade Name: Surfacing Primer
16. Hazardous Class/Division: Flammable - Combustible Liquid
17. Identification Number: (E.g. UN2764, NA 2020) UN1866

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | True |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

- Fire/EMS Report #: True
Police Report #: True
In-house cleanup: False
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 23,500.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

True

If yes, how many? 10

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

ERTS was contacted by Composites One - regarding a truck (#2256) fire that occurred on I-35 NB past exit 494 - in Gainesville, TX due to a mechanical failure when the brakes locked up. The caller has requested a contractor out for cleanup and containment of the waste and debris that has impacted asphalt, soil, and grass. The caller advise the fire dept. is on site and has put out the fire. The trailer is completely destroyed. The roads around the incident have been closed off by police who are also on site.

ERTS dispatched an environmental contractor who confirmed the released was contained to the asphalt roadway and soul median. The contractor excavated the impacted area of soil and clean the impacted roadway. All waste was collected, containerized and taken off site for pending disposal.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

NO COMMENTS PROVIDED.

PART VIII - CONTACT INFORMATION

Contact's Name:	Keith Witkowski
Contact's Title:	PM
Business Name and Address:	EMERGENCY RESPONSE AND TRAININGSOLUTIONS 6001 COCHRAN RD STE 300 SOLON OH 44139-3302
E-mail Address:	kwitkowski@ertsonline.com
Telephone Number:	(440)349-2700
Fax Number:	(440)349-2700
Hazmat Registration Number:	
Date:	04/15/2021
Preparer is:	Other - agent for RP



U.S. Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: E-2021040274
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/12/2021
4. Time of Incident (use 24-hour time): 08:30
5. Enter National Response Center Report Number (if applicable): 1302507
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: GAINESVILLE
County: COOKE
State: TX
Zip Code: (if known): 76240
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
I-35 NB past exit 494
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: COMPOSITES ONE LLC
Street: 85 W ALGONQUIN RD STE 600
City: ARLINGTON HEIGHTS
State: IL
Zip Code: 60005-4421
Federal DOT Id Number: Hazmat Registration Number:
11. Shipper/Offeror:
Name: Composites One LLC
Street: 905 Railhead Drive
City: Fort Worth
State: TX
Zip Code: 76177
Waybill/Shipping Paper: 27316930
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: 1700 Westair
City: GAINESVILLE
State: TX
Zip Code: 76240
14. Proper Shipping Name of Hazardous Material: RESIN SOLUTION, FLAMMABLE
15. Technical/Trade Name: Gray Surfacing Primer
16. Hazardous Class/Division: Flammable - Combustible Liquid
17. Identification Number: (E.g. UN2764, NA 2020) UN1866

- 18. Packing Group:** (if applicable) II
- 19. Quantity Released:** (Include Measurement Units) 40 Liquid - Pound
- 20. Was the material shipped as a hazardous waste?** False
If yes, provide the EPA Manifest Number:
- 21. Is this a Toxic by Inhalation (TIH) material?** False
If yes, provide the Hazard Zone:
- 22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate?** False
If yes, provide the Exemption, Approval, or CA number:
- 23. Was this an undeclared hazardous materials shipment?** False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:
Non-Bulk

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: - 104-Body
How Failed: - 303-Burst or Ruptured
Causes of Failure: - Vehicular Crash or Accident Damage

26a. Provide the packaging identification markings, if available.

Identification Markings: 4G

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Packaging Type: Box Material of Construction: Fiberboard Head Type (Drums only):	Packaging Type: Bottle Material of Construction: Metal (any type)
27. Describe the package capacity and the quantity:	
Package Capacity: 40 Liquid - Pound Amount in Package: 40 Liquid - Pound Number in Shipment: 1 Number Failed: 1	Package Capacity: Amount in Package: Number in Shipment: Number Failed:
28. Provide packaging construction and test information, as appropriate: Manufacturer: Serial Number: Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder) Design Pressure: (if Tank Car, CTMV, Portable Tank) Shell Thickness: (if Tank Car, CTMV, Portable Tank) Head Thickness: (if Tank Car, CTMV) Service Pressure: (if Cylinder) If valve or device failed: Type: Model: Manufacturer:	
29. If the packaging is for Radioactive Materials, complete the following: Packaging Category: Packaging Certification: Certification Number: Nuclide(s) Present: Transport Index: Activity: Critical Safety Index:	

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | True |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

- Fire/EMS Report #: True
Police Report #: True
In-house cleanup: False
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 23,500.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

True

If yes, how many? 10

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

ERTS was contacted by Composites One - regarding a truck (#2256) fire that occurred on I-35 NB past exit 494 - in Gainesville, TX due to a mechanical failure when the brakes locked up. The caller has requested a contractor out for cleanup and containment of the waste and debris that has impacted asphalt, soil, and grass. The caller advise the fire dept. is on site and has put out the fire. The trailer is completely destroyed. The roads around the incident have been closed off by police who are also on site.

ERTS dispatched an environmental contractor who confirmed the released was contained to the asphalt roadway and soul median. The contractor excavated the impacted area of soil and clean the impacted roadway. All waste was collected, containerized and taken off site for pending disposal.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

NO COMMENTS PROVIDED.

PART VIII – CONTACT INFORMATION

Contact's Name:	Keith Witkowski
Contact's Title:	PM
Business Name and Address:	EMERGENCY RESPONSE AND TRAININGSOLUTIONS 6001 COCHRAN RD STE 300 SOLON OH 44139-3302
E-mail Address:	kwitkowski@ertsonline.com
Telephone Number:	(440)349-2700
Fax Number:	(440)349-2700
Hazmat Registration Number:	
Date:	04/15/2021
Preparer is:	Other - agent for RP



U.S Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: E-2021040274
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/12/2021
4. Time of Incident (use 24-hour time): 08:30
5. Enter National Response Center Report Number (if applicable): 1302507
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: GAINESVILLE
County: COOKE
State: TX
Zip Code: (if known): 76240
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
I-35 NB past exit 494
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: COMPOSITES ONE LLC
Street: 85 W ALGONQUIN RD STE 600
City: ARLINGTON HEIGHTS
State: IL
Zip Code: 60005-4421
Federal DOT Id Number: Hazmat Registration Number:
11. Shipper/Offeror:
Name: Composites One LLC
Street: 905 Railhead Drive
City: Fort Worth
State: TX
Zip Code: 76177
Waybill/Shipping Paper: 27316930
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: 1700 Westair
City: GAINESVILLE
State: TX
Zip Code: 76240
14. Proper Shipping Name of Hazardous Material: RESIN SOLUTION, FLAMMABLE
15. Technical/Trade Name: Semi Release Agent
16. Hazardous Class/Division: Flammable - Combustible Liquid
17. Identification Number: (E.g. UN2764, NA 2020) UN1866

18. Packing Group: (if applicable)	II
19. Quantity Released: (Include Measurement Units)	10 Liquid - Pound
20. Was the material shipped as a hazardous waste?	False
If yes, provide the EPA Manifest Number:	
21. Is this a Toxic by Inhalation (TIH) material?	False
If yes, provide the Hazard Zone:	
22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate?	False
If yes, provide the Exemption, Approval, or CA number:	
23. Was this an undeclared hazardous materials shipment?	False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:
Non-Bulk

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.
Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed:	- 104-Body
How Failed:	- 303-Burst or Ruptured
Causes of Failure:	- Vehicular Crash or Accident Damage

26a. Provide the packaging identification markings, if available.
Identification Markings: 4G
(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:		Single Package or Inner Packaging (if any):	
Packaging Type:	Box	Packaging Type:	Bottle
Material of Construction:	Fiberboard	Material of Construction:	Metal (any type)
Head Type (Drums only):			
27. Describe the package capacity and the quantity:			
Single Package or Outer Packaging:		Single Package or Inner Packaging (if any):	
Package Capacity:	10 Liquid - Pound	Package Capacity:	
Amount in Package:	10 Liquid - Pound	Amount in Package:	
Number in Shipment:	1	Number in Shipment:	
Number Failed:	1	Number Failed:	
28. Provide packaging construction and test information, as appropriate:			
Manufacturer:		Manufacture Date:	
Serial Number:		Last Test Date:	
Material of Construction:	(if Tank Car, CTMV, Portable Tank, or Cylinder)		
Design Pressure:	(if Tank Car, CTMV, Portable Tank)		
Shell Thickness:	(if Tank Car, CTMV, Portable Tank)		
Head Thickness:	(if Tank Car, CTMV)		
Service Pressure:	(if Cylinder)		
If valve or device failed:			
Type:			
Model:			
Manufacturer:			
29. If the packaging is for Radioactive Materials, complete the following:			
Packaging Category:			
Packaging Certification:			
Certification Number:			
Nuclide(s) Present:		Transport Index:	
Activity:			
Critical Safety Index:			

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | True |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

- Fire/EMS Report #: True
Police Report #: True
In-house cleanup: False
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 23,500.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

True

If yes, how many? 10

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

ERTS was contacted by Composites One - regarding a truck (#2256) fire that occurred on I-35 NB past exit 494 - in Gainesville, TX due to a mechanical failure when the brakes locked up. The caller has requested a contractor out for cleanup and containment of the waste and debris that has impacted asphalt, soil, and grass. The caller advise the fire dept. is on site and has put out the fire. The trailer is completely destroyed. The roads around the incident have been closed off by police who are also on site.

ERTS dispatched an environmental contractor who confirmed the released was contained to the asphalt roadway and soul median. The contractor excavated the impacted area of soil and clean the impacted roadway. All waste was collected, containerized and taken off site for pending disposal.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

NO COMMENTS PROVIDED.

PART VIII - CONTACT INFORMATION

Contact's Name:	Keith Witkowski
Contact's Title:	PM
Business Name and Address:	EMERGENCY RESPONSE AND TRAININGSOLUTIONS 6001 COCHRAN RD STE 300 SOLON OH 44139-3302
E-mail Address:	kwitkowski@ertsonline.com
Telephone Number:	(440)349-2700
Fax Number:	(440)349-2700
Hazmat Registration Number:	
Date:	04/15/2021
Preparer is:	Other - agent for RP



U.S Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: E-2021040274
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/12/2021
4. Time of Incident (use 24-hour time): 08:30
5. Enter National Response Center Report Number (if applicable): 1302507
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: GAINESVILLE
County: COOKE
State: TX
Zip Code: (if known): 76240
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
I-35 NB past exit 494
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: COMPOSITES ONE LLC
Street: 85 W ALGONQUIN RD STE 600
City: ARLINGTON HEIGHTS
State: IL
Zip Code: 60005-4421
Federal DOT Id Number: Hazmat Registration Number:
11. Shipper/Offeror:
Name: Composites One LLC
Street: 905 Railhead Drive
City: Fort Worth
State: TX
Zip Code: 76177
Waybill/Shipping Paper: 27316930
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: 1700 Westair
City: GAINESVILLE
State: TX
Zip Code: 76240
14. Proper Shipping Name of Hazardous Material: RESIN SOLUTION, FLAMMABLE
15. Technical/Trade Name: GL15 Sealer
16. Hazardous Class/Division: Flammable - Combustible Liquid
17. Identification Number: (E.g. UN2764, NA 2020) UN1866

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | True |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

- Fire/EMS Report #: True
Police Report #: True
In-house cleanup: False
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 23,500.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

True

If yes, how many? 10

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

ERTS was contacted by Composites One - regarding a truck (#2256) fire that occurred on I-35 NB past exit 494 - in Gainesville, TX due to a mechanical failure when the brakes locked up. The caller has requested a contractor out for cleanup and containment of the waste and debris that has impacted asphalt, soil, and grass. The caller advise the fire dept. is on site and has put out the fire. The trailer is completely destroyed. The roads around the incident have been closed off by police who are also on site.

ERTS dispatched an environmental contractor who confirmed the released was contained to the asphalt roadway and soul median. The contractor excavated the impacted area of soil and clean the impacted roadway. All waste was collected, containerized and taken off site for pending disposal.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

NO COMMENTS PROVIDED.

PART VIII - CONTACT INFORMATION

Contact's Name:	Keith Witkowski
Contact's Title:	PM
Business Name and Address:	EMERGENCY RESPONSE AND TRAININGSOLUTIONS 6001 COCHRAN RD STE 300 SOLON OH 44139-3302
E-mail Address:	kwitkowski@ertsonline.com
Telephone Number:	(440)349-2700
Fax Number:	(440)349-2700
Hazmat Registration Number:	
Date:	04/15/2021
Preparer is:	Other - agent for RP



U.S Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: E-2021040274
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/12/2021
4. Time of Incident (use 24-hour time): 08:30
5. Enter National Response Center Report Number (if applicable): 1302507
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: GAINESVILLE
County: COOKE
State: TX
Zip Code: (if known): 76240
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
I-35 NB past exit 494
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: COMPOSITES ONE LLC
Street: 85 W ALGONQUIN RD STE 600
City: ARLINGTON HEIGHTS
State: IL
Zip Code: 60005-4421
Federal DOT Id Number: Hazmat Registration Number:
11. Shipper/Offeror:
Name: Composites One LLC
Street: 905 Railhead Drive
City: Fort Worth
State: TX
Zip Code: 76177
Waybill/Shipping Paper: 27316930
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: 1700 Westair
City: GAINESVILLE
State: TX
Zip Code: 76240
14. Proper Shipping Name of Hazardous Material: ORGANIC PEROXIDE TYPE D, LIQUID
15. Technical/Trade Name: Luperox DDM-9
16. Hazardous Class/Division: Organic Peroxide
17. Identification Number: (E.g. UN2764, NA 2020) UN3105

18. Packing Group: (if applicable)

19. Quantity Released: (Include Measurement Units) 40 Liquid - Pound

20. Was the material shipped as a hazardous waste? False
If yes, provide the EPA Manifest Number:

21. Is this a Toxic by Inhalation (TIH) material? False
If yes, provide the Hazard Zone:

22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate? False
If yes, provide the Exemption, Approval, or CA number:

23. Was this an undeclared hazardous materials shipment? False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:
Non-Bulk

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.
Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: - 104-Body
How Failed: - 303-Burst or Ruptured
Causes of Failure: - Vehicular Crash or Accident Damage

26a. Provide the packaging identification markings, if available.

Identification Markings: 4G

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Packaging Type: Box Material of Construction: Fiberboard Head Type (Drums only):	Packaging Type: Bottle Material of Construction: Metal (any type)
27. Describe the package capacity and the quantity:	
Package Capacity: 40 Liquid - Pound Amount in Package: 40 Liquid - Pound Number in Shipment: 1 Number Failed: 1	Package Capacity: Amount in Package: Number in Shipment: Number Failed:
28. Provide packaging construction and test information, as appropriate: Manufacturer: Serial Number: Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder) Design Pressure: (if Tank Car, CTMV, Portable Tank) Shell Thickness: (if Tank Car, CTMV, Portable Tank) Head Thickness: (if Tank Car, CTMV) Service Pressure: (if Cylinder) If valve or device failed: Type: Model: Manufacturer:	
29. If the packaging is for Radioactive Materials, complete the following: Packaging Category: Packaging Certification: Certification Number: Nuclide(s) Present: Transport Index: Activity: Critical Safety Index:	

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | True |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

- Fire/EMS Report #: True
Police Report #: True
In-house cleanup: False
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 23,500.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

True

If yes, how many? 10

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

ERTS was contacted by Composites One - regarding a truck (#2256) fire that occurred on I-35 NB past exit 494 - in Gainesville, TX due to a mechanical failure when the brakes locked up. The caller has requested a contractor out for cleanup and containment of the waste and debris that has impacted asphalt, soil, and grass. The caller advise the fire dept. is on site and has put out the fire. The trailer is completely destroyed. The roads around the incident have been closed off by police who are also on site.

ERTS dispatched an environmental contractor who confirmed the released was contained to the asphalt roadway and soul median. The contractor excavated the impacted area of soil and clean the impacted roadway. All waste was collected, containerized and taken off site for pending disposal.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

NO COMMENTS PROVIDED.

PART VIII – CONTACT INFORMATION

Contact's Name:	Keith Witkowski
Contact's Title:	PM
Business Name and Address:	EMERGENCY RESPONSE AND TRAININGSOLUTIONS 6001 COCHRAN RD STE 300 SOLON OH 44139-3302
E-mail Address:	kwitkowski@ertsonline.com
Telephone Number:	(440)349-2700
Fax Number:	(440)349-2700
Hazmat Registration Number:	
Date:	04/15/2021
Preparer is:	Other - agent for RP



U.S Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: E-2021040274
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/12/2021
4. Time of Incident (use 24-hour time): 08:30
5. Enter National Response Center Report Number (if applicable): 1302507
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: GAINESVILLE
County: COOKE
State: TX
Zip Code: (if known): 76240
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
I-35 NB past exit 494
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: COMPOSITES ONE LLC
Street: 85 W ALGONQUIN RD STE 600
City: ARLINGTON HEIGHTS
State: IL
Zip Code: 60005-4421
Federal DOT Id Number: Hazmat Registration Number:
11. Shipper/Offeror:
Name: Composites One LLC
Street: 905 Railhead Drive
City: Fort Worth
State: TX
Zip Code: 76177
Waybill/Shipping Paper: 27316930
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: 1700 Westair
City: GAINESVILLE
State: TX
Zip Code: 76240
14. Proper Shipping Name of Hazardous Material: ACETONE
15. Technical/Trade Name: Acetone
16. Hazardous Class/Division: Flammable - Combustible Liquid
17. Identification Number: (E.g. UN2764, NA 2020) UN1090

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | True |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

- Fire/EMS Report #: True
Police Report #: True
In-house cleanup: False
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 23,500.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

True

If yes, how many? 10

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

ERTS was contacted by Composites One - regarding a truck (#2256) fire that occurred on I-35 NB past exit 494 - in Gainesville, TX due to a mechanical failure when the brakes locked up. The caller has requested a contractor out for cleanup and containment of the waste and debris that has impacted asphalt, soil, and grass. The caller advise the fire dept. is on site and has put out the fire. The trailer is completely destroyed. The roads around the incident have been closed off by police who are also on site.

ERTS dispatched an environmental contractor who confirmed the released was contained to the asphalt roadway and soul median. The contractor excavated the impacted area of soil and clean the impacted roadway. All waste was collected, containerized and taken off site for pending disposal.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

NO COMMENTS PROVIDED.

PART VIII – CONTACT INFORMATION

Contact's Name:	Keith Witkowski
Contact's Title:	PM
Business Name and Address:	EMERGENCY RESPONSE AND TRAININGSOLUTIONS 6001 COCHRAN RD STE 300 SOLON OH 44139-3302
E-mail Address:	kwitkowski@ertsonline.com
Telephone Number:	(440)349-2700
Fax Number:	(440)349-2700
Hazmat Registration Number:	
Date:	04/15/2021
Preparer is:	Other - agent for RP



U.S Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: E-2021040274
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/12/2021
4. Time of Incident (use 24-hour time): 08:30
5. Enter National Response Center Report Number (if applicable): 1302507
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: GAINESVILLE
County: COOKE
State: TX
Zip Code: (if known): 76240
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
I-35 NB past exit 494
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: COMPOSITES ONE LLC
Street: 85 W ALGONQUIN RD STE 600
City: ARLINGTON HEIGHTS
State: IL
Zip Code: 60005-4421
Federal DOT Id Number: Hazmat Registration Number:
11. Shipper/Offeror:
Name: Composites One LLC
Street: 905 Railhead Drive
City: Fort Worth
State: TX
Zip Code: 76177
Waybill/Shipping Paper: 27316930
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: 1700 Westair
City: GAINESVILLE
State: TX
Zip Code: 76240
14. Proper Shipping Name of Hazardous Material: FLAMMABLE LIQUIDS, N.O.S.
15. Technical/Trade Name: GE Mold Cleaner
16. Hazardous Class/Division: Flammable - Combustible Liquid
17. Identification Number: (E.g. UN2764, NA 2020) UN1993

- 18. Packing Group:** (if applicable) II
- 19. Quantity Released:** (Include Measurement Units) 40 Liquid - Pound
- 20. Was the material shipped as a hazardous waste?** False
If yes, provide the EPA Manifest Number:
- 21. Is this a Toxic by Inhalation (TIH) material?** False
If yes, provide the Hazard Zone:
- 22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate?** False
If yes, provide the Exemption, Approval, or CA number:
- 23. Was this an undeclared hazardous materials shipment?** False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:
Non-Bulk

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: - 104-Body
How Failed: - 303-Burst or Ruptured
Causes of Failure: - Vehicular Crash or Accident Damage

26a. Provide the packaging identification markings, if available.

Identification Markings: 4G

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Packaging Type: Box Material of Construction: Fiberboard Head Type (Drums only):	Packaging Type: Bottle Material of Construction: Metal (any type)
27. Describe the package capacity and the quantity:	
Single Package or Outer Packaging:	Single Package or Inner Packaging (if any):
Package Capacity: 40 Liquid - Pound Amount in Package: 40 Liquid - Pound Number in Shipment: 1 Number Failed: 1	Package Capacity: Amount in Package: Number in Shipment: Number Failed:
28. Provide packaging construction and test information, as appropriate: Manufacturer: Serial Number: Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder) Design Pressure: (if Tank Car, CTMV, Portable Tank) Shell Thickness: (if Tank Car, CTMV, Portable Tank) Head Thickness: (if Tank Car, CTMV) Service Pressure: (if Cylinder) If valve or device failed: Type: Model: Manufacturer:	
29. If the packaging is for Radioactive Materials, complete the following: Packaging Category: Packaging Certification: Certification Number: Nuclide(s) Present: Transport Index: Activity: Critical Safety Index:	

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | True |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

- Fire/EMS Report #: True
Police Report #: True
In-house cleanup: False
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 23,500.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

True

If yes, how many? 10

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

ERTS was contacted by Composites One - regarding a truck (#2256) fire that occurred on I-35 NB past exit 494 - in Gainesville, TX due to a mechanical failure when the brakes locked up. The caller has requested a contractor out for cleanup and containment of the waste and debris that has impacted asphalt, soil, and grass. The caller advise the fire dept. is on site and has put out the fire. The trailer is completely destroyed. The roads around the incident have been closed off by police who are also on site.

ERTS dispatched an environmental contractor who confirmed the released was contained to the asphalt roadway and soul median. The contractor excavated the impacted area of soil and clean the impacted roadway. All waste was collected, containerized and taken off site for pending disposal.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

NO COMMENTS PROVIDED.

PART VIII - CONTACT INFORMATION

Contact's Name:	Keith Witkowski
Contact's Title:	PM
Business Name and Address:	EMERGENCY RESPONSE AND TRAININGSOLUTIONS 6001 COCHRAN RD STE 300 SOLON OH 44139-3302
E-mail Address:	kwitkowski@ertsonline.com
Telephone Number:	(440)349-2700
Fax Number:	(440)349-2700
Hazmat Registration Number:	
Date:	04/15/2021
Preparer is:	Other - agent for RP



U.S Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: E-2021040274
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/12/2021
4. Time of Incident (use 24-hour time): 08:30
5. Enter National Response Center Report Number (if applicable): 1302507
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: GAINESVILLE
County: COOKE
State: TX
Zip Code: (if known): 76240
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
I-35 NB past exit 494
8. Mode of Transportation: Highway
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: COMPOSITES ONE LLC
Street: 85 W ALGONQUIN RD STE 600
City: ARLINGTON HEIGHTS
State: IL
Zip Code: 60005-4421
Federal DOT Id Number: Hazmat Registration Number:
11. Shipper/Offeror:
Name: Composites One LLC
Street: 905 Railhead Drive
City: Fort Worth
State: TX
Zip Code: 76177
Waybill/Shipping Paper: 27316930
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: 3333 N LH 35
City: GAINESVILLE
State: TX
Zip Code: 76240
14. Proper Shipping Name of Hazardous Material: ORGANIC PEROXIDE TYPE D, LIQUID
15. Technical/Trade Name: Cadox D-50 Clear
16. Hazardous Class/Division: Organic Peroxide
17. Identification Number: (E.g. UN2764, NA 2020) UN3105

23. Was this an undeclared hazardous materials shipment? False

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | True |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

- Fire/EMS Report #: True
Police Report #: True
In-house cleanup: False
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 23,500.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

True

If yes, how many? 10

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

ERTS was contacted by Composites One - regarding a truck (#2256) fire that occurred on I-35 NB past exit 494 - in Gainesville, TX due to a mechanical failure when the brakes locked up. The caller has requested a contractor out for cleanup and containment of the waste and debris that has impacted asphalt, soil, and grass. The caller advise the fire dept. is on site and has put out the fire. The trailer is completely destroyed. The roads around the incident have been closed off by police who are also on site.

ERTS dispatched an environmental contractor who confirmed the released was contained to the asphalt roadway and soul median. The contractor excavated the impacted area of soil and clean the impacted roadway. All waste was collected, containerized and taken off site for pending disposal.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

NO COMMENTS PROVIDED.

PART VIII - CONTACT INFORMATION

Contact's Name:	Keith Witkowski
Contact's Title:	PM
Business Name and Address:	EMERGENCY RESPONSE AND TRAININGSOLUTIONS 6001 COCHRAN RD STE 300 SOLON OH 44139-3302
E-mail Address:	kwitkowski@ertsonline.com
Telephone Number:	(440)349-2700
Fax Number:	(440)349-2700
Hazmat Registration Number:	
Date:	04/15/2021
Preparer is:	Other - agent for RP