



U.S. Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: I-2008070222
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident:
01/15/2008

4. Time of Incident (use 24-hour time):
03:00

5. Enter National Response Center Report Number (if applicable):

6. If you submitted a report to another Federal DOT agency, enter the agency and report number:

7. Location of Incident:

City: WINNIE
County: CHAMBERS
State: TX
Zip Code: (if known): 77665
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
130 WILLARD STREET

8. Mode of Transportation: Highway

9. Transportation Phase: In Transit

10. Carrier/Reporter:

Name: KLLM TRANSPORT SERVICES
Street: 135 RIVERVIEW DR
City: RICHLAND
State: MS
Zip Code: 39218
Federal DOT Id Number: 86953
Hazmat Registration Number: 060303008002LN

11. Shipper/Officer:

Name: DELTA CHEMICAL
Street: 10521 SHELDON RD
City: HOUSTON
State: TX
Zip Code: 77044
Waybill/Shipping Paper:
Hazmat Registration Number: 0521075500690

12. Origin (if different from shipper address)

Street: 5500 BENEX DRIVE
City: INVER GROVE HEIGHTS
State: MN
Zip Code: 55077

13. Destination:

Street: 1750 OVERVIEW DR
City: ROCK HILL
State: SC
Zip Code: 29731

14. Proper Shipping Name of Hazardous Material: CORROSIVE LIQUID, ACIDIC, ORGANIC, N.O.S.

15. Technical/Trade Name: NOIBN 60000

16. Hazardous Class/Division: Corrosive Material

17. Identification Number: (E.g. UN2764, NA 2020) UN3265

- 18. Packing Group:** (if applicable) II
- 19. Quantity Released:** (Include Measurement Units) 2400 Liquid - Gallon
- 20. Was the material shipped as a hazardous waste?** False
If yes, provide the EPA Manifest Number:
- 21. Is this a Toxic by Inhalation (TIH) material?** False
If yes, provide the Hazard Zone:
- 22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate?** False
If yes, provide the Exemption, Approval, or CA number:
- 23. Was this an undeclared hazardous materials shipment?** False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:

Other, 55 GAL DRUMS

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: - 124-High Level Sensor
How Failed: - 306-Failed to Operate
Causes of Failure: - Human Error

26a. Provide the packaging identification markings, if available.

Identification Markings: NO MARKINGS GIVEN

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Packaging Type:
Material of Construction:
Head Type (Drums only):

Packaging Type:
Material of Construction:

27. Describe the package capacity and the quantity:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Package Capacity: 55 Liquid - Gallon
Amount in Package: 55 Liquid - Gallon
Number in Shipment: 68
Number Failed: 45

Package Capacity:
Amount in Package:
Number in Shipment:
Number Failed:

28. Provide packaging construction and test information, as appropriate:

Manufacturer:
Serial Number: 5033
Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder)
Design Pressure: (if Tank Car, CTMV, Portable Tank)
Shell Thickness: (if Tank Car, CTMV, Portable Tank)
Head Thickness: (if Tank Car, CTMV)
Service Pressure: (if Cylinder)
If valve or device failed:
Type:
Model:
Manufacturer:

Manufacture Date: 02/01/1991
Last Test Date:

29. If the packaging is for Radioactive Materials, complete the following:

Packaging Category:
Packaging Certification:
Certification Number:
Nuclide(s) Present:
Activity:
Critical Safety Index:

Transport Index:

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | False | - Fire: | True |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | True |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

- Fire/EMS Report #: True
Police Report #: False
In-house cleanup: False
Other Cleanup: True

32. Damages Was the total damage cost more than \$500?

True

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 37,600.00
Carrier Damage: \$ 30,000.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 100,000.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many? 0

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated:
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

True

If yes, how many? 2

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

On January 15th , 2008, at approximately 3:00 a.m. CST, a tractor-trailer operated by KLLM Transport Services, was traveling on 1-10 west at approximately mile marker 817 when the driver noticed a rear trailer tire was on fire. The driver immediately pulled over and attempted to extinguish the fire. The fire began to intensify so the driver dropped the trailer and pulled the tractor forward. Apparently, the brake hub had locked up causing the fire. The driver then notified his dispatch of the incident and called 911. The trailer contained sixty-two (62), 55-gallon drums of methane sulfonic acid.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

Apparently, the brake hub had locked up causing the trailer fire. The driver then notified his dispatch of the incident and called 911.

PART VIII – CONTACT INFORMATION

Contact's Name:	MS GWEN HEMPHILL
Contact's Title:	CLAIMS
Business Name and Address:	KLLM TRANSPORT SERVICES GREENVILLE SC 29601
E-mail Address:	ghemphill@kllm.COM
Telephone Number:	8006710809
Fax Number:	8642821975
Hazmat Registration Number:	
Date:	03/28/2008
Preparer is:	Other - CONSULTANT

02/01/1991