



U.S. Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: I-1998061440
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/26/1998
4. Time of Incident (use 24-hour time): 11:55
5. Enter National Response Center Report Number (if applicable):
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: HOUSTON
County: FORT BEND
State: TX
Zip Code: (if known):
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
8. Mode of Transportation: Water
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: SEA-LAND SERVICE INC
Street: 2700 FRANCE ROAD
City: NEW ORLEANS
State: LA
Zip Code: 70126
Federal DOT Id Number:
Hazmat Registration Number:
11. Shipper/Officer:
Name: CONCENTRATE MFG CO OF PR THE
Street: PO BOX 1558
City: CIDRA PR
State: ZZ
Zip Code: 00739
Waybill/Shipping Paper: 796630887
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: 15 AVENDIA 7MA CALLE SO
City: SAN PDRO SULA
State: ZZ
Zip Code:
14. Proper Shipping Name of Hazardous Material: PHOSPHORIC ACID SOLUTION
15. Technical/Trade Name: PHOSPHORIC ACID
16. Hazardous Class/Division: Corrosive Material
17. Identification Number: (E.g. UN2764, NA 2020) UN1805

18. Packing Group: (if applicable)

19. Quantity Released: (Include Measurement Units) 22.5 Liquid - Gallon

20. Was the material shipped as a hazardous waste?

If yes, provide the EPA Manifest Number:

21. Is this a Toxic by Inhalation (TIH) material?

If yes, provide the Hazard Zone:

22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate?

If yes, provide the Exemption, Approval, or CA number:

23. Was this an undeclared hazardous materials shipment?

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:

Non-Bulk

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: -

How Failed: -

Causes of Failure: -

26a. Provide the packaging identification markings, if available.

Identification Markings:

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Packaging Type:
Material of Construction:
Head Type (Drums only):

Packaging Type:
Material of Construction:

27. Describe the package capacity and the quantity:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Package Capacity: 4.5 Liquid - Gallon
Amount in Package:
Number in Shipment: 408
Number Failed: 5

Package Capacity:
Amount in Package:
Number in Shipment:
Number Failed:

28. Provide packaging construction and test information, as appropriate:

Manufacturer: NOT REPORTED BY CARRIER
Serial Number:
Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder)
Design Pressure: (if Tank Car, CTMV, Portable Tank)
Shell Thickness: (if Tank Car, CTMV, Portable Tank)
Head Thickness: (if Tank Car, CTMV)
Service Pressure: (if Cylinder)
If valve or device failed:
Type:
Model:
Manufacturer:

Manufacture Date:
Last Test Date:

29. If the packaging is for Radioactive Materials, complete the following:

Packaging Category:
Packaging Certification:
Certification Number:
Nuclide(s) Present:
Activity:
Critical Safety Index:

Transport Index:

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | False |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

Fire/EMS Report #:
Police Report #:
In-house cleanup:
Other Cleanup:

32. Damages Was the total damage cost more than \$500? False

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 0.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality? False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material? False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury? False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation? False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed? False

If yes, how many?

37. Was the material involved in a crash or derailment? False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

SEA-LAND SERVICE, INC. ISSUED A BILL OF LADING FOR THE TRANSPORTATION OF THIS CARGO. SEA-LAND CONTRACTED WITH MCALLISTER TOWING AND TRANSPORTATION COMPANY INC TO TRANSPORT THE CARGO ON THE HOUSTON TO NEW ORLEANS LEG OF THE CARRIAGE. THE CARGO WAS LOADED ABOARD MCALLISTER TOWING AND TRANSPORTATION COMPANY, INC.'S BARGE, THE CHESAPEAKE TRADER, AT HOUSTON AND SECURED WITH EQUIPMENT SUPPLIED BY COLUMBIA COASTAL TRANSPORT, LLC, TO THE SATIFICATION OF THE MASTER OF THE M/V CAPT BILL, THE TUG WHICH TOWED THE BARGE. THE M/V CAPT. BILL WAS CHARTERED FROM MCALLISTER TOWING AND TRANSPORTATION COMPANY INC. ALL DECISIONS REGARDING DEPARTURE TIME, ROUTE AND NAVIGATION OF THE TUG AND TOW WERE MADE BY THE MASTER OF THE VESSEL. SEA-LAND HAS NO FIRST HAND INFORMATION WITH REGARDS TO THE EVENTS FOLLOWING DEPARTURE OF THE TUG AND TOW FROM HOUSTON, UNTIL THE FLOTILLA'S ARRIVAL IN NEW ORLEANS. HOWEVER, REVIEW OF THE DECK LOG OF THE TUG CAPT. BILL INDICATES THAT 1155 HOURS ON SUNDAY, APRIL 26, 1998, WHILE THE VESSEL WAS LOCATED AT LATITUDE 28 46.9'N AND LONGITUDE 92 18.1'W, 9 CONTAINERS FROM HATCH 1 WERE LOST OVERBOARD. ADDITIONAL CONTAINERS FROM HATCHES 1 AND 2 WERE LOST OVERBOARD AS THE VESSEL CONTINUED EAST. THE CONTAINER CONTAINING THIS MATERIAL WAS FOUND TO BE DAMAGED AND LEAKING ON ARRIVAL IN NEW ORLEANS.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

PART VIII – CONTACT INFORMATION

Contact's Name: JOE GALLEGO
Contact's Title: MGR CNT YARD SAFETY
Business Name and Address:

E-mail Address:
Telephone Number: 504-948-0245
Fax Number:
Hazmat Registration Number:
Date: 05/26/1998
Preparer is:



U.S. Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: I-1998061440
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/26/1998
4. Time of Incident (use 24-hour time): 11:55
5. Enter National Response Center Report Number (if applicable):
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: HOUSTON
County: FORT BEND
State: TX
Zip Code: (if known):
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
8. Mode of Transportation: Water
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: SEA-LAND SERVICE INC
Street: 2700 FRANCE ROAD
City: NEW ORLEANS
State: LA
Zip Code: 70126
Federal DOT Id Number:
Hazmat Registration Number:
11. Shipper/Officer:
Name: CONCENTRATE MFG CO OF PR THE
Street: PO BOX 1558
City: CIDRA PR
State: ZZ
Zip Code: 00739
Waybill/Shipping Paper: 796630887
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street:
City: HONDURAS
State: ZZ
Zip Code:
14. Proper Shipping Name of Hazardous Material: EXTRACTS, FLAVORING, LIQUID
15. Technical/Trade Name: EXTRACT FLAVORING LI
16. Hazardous Class/Division: Flammable - Combustible Liquid
17. Identification Number: (E.g. UN2764, NA 2020) UN1197

18. Packing Group: (if applicable)

19. Quantity Released: (Include Measurement Units) 400 Liquid - Gallon

20. Was the material shipped as a hazardous waste?

If yes, provide the EPA Manifest Number:

21. Is this a Toxic by Inhalation (TIH) material?

If yes, provide the Hazard Zone:

22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate?

If yes, provide the Exemption, Approval, or CA number:

23. Was this an undeclared hazardous materials shipment?

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:

Non-Bulk

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: -

How Failed: -

Causes of Failure: -

26a. Provide the packaging identification markings, if available.

Identification Markings:

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Packaging Type:
Material of Construction:
Head Type (Drums only):

Packaging Type:
Material of Construction:

27. Describe the package capacity and the quantity:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Package Capacity: 4 Liquid - Gallon
Amount in Package:
Number in Shipment: 100
Number Failed: 100

Package Capacity: 4 Liquid - Gallon
Amount in Package:
Number in Shipment: 100
Number Failed: 100

28. Provide packaging construction and test information, as appropriate:

Manufacturer: NOT REPORTED BY CARRIER
Serial Number:
Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder)
Design Pressure: (if Tank Car, CTMV, Portable Tank)
Shell Thickness: (if Tank Car, CTMV, Portable Tank)
Head Thickness: (if Tank Car, CTMV)
Service Pressure: (if Cylinder)
If valve or device failed:
Type:
Model:
Manufacturer:

Manufacture Date:
Last Test Date:

29. If the packaging is for Radioactive Materials, complete the following:

Packaging Category:
Packaging Certification:
Certification Number:
Nuclide(s) Present:
Activity:
Critical Safety Index:

Transport Index:

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | False |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

Fire/EMS Report #:
Police Report #:
In-house cleanup:
Other Cleanup:

32. Damages Was the total damage cost more than \$500?

False

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 0.00

(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

False

If yes, how many?

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

SEA-LAND SERVICE, INC. ISSUED A BILL OF LADING FOR THE TRANSPORTATION OF THIS CARGO. SEA-LAND CONTRACTED WITH MCALLISTER TOWING AND TRANSPORTATION COMPANY INC TO TRANSPORT THE CARGO ON THE HOUSTON TO NEW ORLEANS LEG OF THE CARRIAGE. THE CARGO WAS LOADED ABOARD MCALLISTER TOWING AND TRANSPORTATION COMPANY, INC.'S BARGE, THE CHESAPEAKE TRADER, AT HOUSTON AND SECURED WITH EQUIPMENT SUPPLIED BY COLUMBIA COASTAL TRANSPORT, LLC, TO THE SATIFICATION OF THE MASTER OF THE M/V CAPT BILL, THE TUG WHICH TOWED THE BARGE. THE M/V CAPT. BILL WAS CHARTERED FROM MCALLISTER TOWING AND TRANSPORTATION COMPANY INC. ALL DECISIONS REGARDING DEPARTURE TIME, ROUTE AND NAVIGATION OF THE TUG AND TOW WERE MADE BY THE MASTER OF THE VESSEL. SEA-LAND HAS NO FIRST HAND INFORMATION WITH REGARDS TO THE EVENTS FOLLOWING DEPARTURE OF THE TUG AND TOW FROM HOUSTON, UNTIL THE FLOTILLA'S ARRIVAL IN NEW ORLEANS. HOWEVER, REVIEW OF THE DECK LOG OF THE TUG CAPT. BILL INDICATES THAT 1155 HOURS ON SUNDAY, APRIL 26, 1998, WHILE THE VESSEL WAS LOCATED AT LATITUDE 28 46.9'N AND LONGITUDE 92 18.1'W, 9 CONTAINERS FROM HATCH 1 WERE LOST OVERBOARD. ADDITIONAL CONTAINERS FROM HATCHES 1 AND 2 WERE LOST OVERBOARD AS THE VESSEL CONTINUED EAST. THE CONTAINER CONTAINING THIS MATERIAL WAS FOUND TO BE DAMAGED AND LEAKING ON ARRIVAL IN NEW ORLEANS.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

PART VIII – CONTACT INFORMATION

Contact's Name: JOE GALLEGO
Contact's Title: MGR CNT YARD SAFETY
Business Name and Address:

E-mail Address:
Telephone Number: 504-948-0245
Fax Number:
Hazmat Registration Number:
Date: 05/26/1998
Preparer is:



U.S. Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: I-1998061440
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/26/1998
4. Time of Incident (use 24-hour time): 11:55
5. Enter National Response Center Report Number (if applicable):
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: HOUSTON
County: FORT BEND
State: TX
Zip Code: (if known):
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
8. Mode of Transportation: Water
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: SEA-LAND SERVICE INC
Street: 2700 FRANCE ROAD
City: NEW ORLEANS
State: LA
Zip Code: 70126
Federal DOT Id Number:
Hazmat Registration Number:
11. Shipper/Officer:
Name: CONCENTRATE MFG CO OF PR THE
Street: PO BOX 1558
City: CIDRA PR
State: ZZ
Zip Code: 00739
Waybill/Shipping Paper: 796630887
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: AVENDIA LA REFORMA 9-30
City: GUATEMALA
State: ZZ
Zip Code:
14. Proper Shipping Name of Hazardous Material: PHOSPHORIC ACID SOLUTION
15. Technical/Trade Name:
16. Hazardous Class/Division: Corrosive Material
17. Identification Number: (E.g. UN2764, NA 2020) UN1805

18. Packing Group: (if applicable)

19. Quantity Released: (Include Measurement Units) 36 Liquid - Gallon

20. Was the material shipped as a hazardous waste?

If yes, provide the EPA Manifest Number:

21. Is this a Toxic by Inhalation (TIH) material?

If yes, provide the Hazard Zone:

22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate?

If yes, provide the Exemption, Approval, or CA number:

23. Was this an undeclared hazardous materials shipment?

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:

Non-Bulk

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: -

How Failed: -

Causes of Failure: -

26a. Provide the packaging identification markings, if available.

Identification Markings:

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Packaging Type:
Material of Construction:
Head Type (Drums only):

Packaging Type:
Material of Construction:

27. Describe the package capacity and the quantity:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Package Capacity: 4.5 Liquid - Gallon
Amount in Package:
Number in Shipment: 8
Number Failed: 8

Package Capacity:
Amount in Package:
Number in Shipment:
Number Failed:

28. Provide packaging construction and test information, as appropriate:

Manufacturer: NOT REPORTED BY CARRIER
Serial Number:
Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder)
Design Pressure: (if Tank Car, CTMV, Portable Tank)
Shell Thickness: (if Tank Car, CTMV, Portable Tank)
Head Thickness: (if Tank Car, CTMV)
Service Pressure: (if Cylinder)
If valve or device failed:
Type:
Model:
Manufacturer:

Manufacture Date:
Last Test Date:

29. If the packaging is for Radioactive Materials, complete the following:

Packaging Category:
Packaging Certification:
Certification Number:
Nuclide(s) Present:
Activity:
Critical Safety Index:

Transport Index:

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | False |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

Fire/EMS Report #:
Police Report #:
In-house cleanup:
Other Cleanup:

32. Damages Was the total damage cost more than \$500?

False

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 0.00

(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury?

False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

False

If yes, how many?

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

SEA-LAND SERVICE, INC. ISSUED A BILL OF LADING FOR THE TRANSPORTATION OF THIS CARGO. SEA-LAND CONTRACTED WITH MCALLISTER TOWING AND TRANSPORTATION COMPANY INC TO TRANSPORT THE CARGO ON THE HOUSTON TO NEW ORLEANS LEG OF THE CARRIAGE. THE CARGO WAS LOADED ABOARD MCALLISTER TOWING AND TRANSPORTATION COMPANY, INC.'S BARGE, THE CHESAPEAKE TRADER, AT HOUSTON AND SECURED WITH EQUIPMENT SUPPLIED BY COLUMBIA COASTAL TRANSPORT, LLC, TO THE SATIFICATION OF THE MASTER OF THE M/V CAPT BILL, THE TUG WHICH TOWED THE BARGE. THE M/V CAPT. BILL WAS CHARTERED FROM MCALLISTER TOWING AND TRANSPORTATION COMPANY INC. ALL DECISIONS REGARDING DEPARTURE TIME, ROUTE AND NAVIGATION OF THE TUG AND TOW WERE MADE BY THE MASTER OF THE VESSEL. SEA-LAND HAS NO FIRST HAND INFORMATION WITH REGARDS TO THE EVENTS FOLLOWING DEPARTURE OF THE TUG AND TOW FROM HOUSTON, UNTIL THE FLOTILLA'S ARRIVAL IN NEW ORLEANS. HOWEVER, REVIEW OF THE DECK LOG OF THE TUG CAPT. BILL INDICATES THAT 1155 HOURS ON SUNDAY, APRIL 26, 1998, WHILE THE VESSEL WAS LOCATED AT LATITUDE 28 46.9'N AND LONGITUDE 92 18.1'W, 9 CONTAINERS FROM HATCH 1 WERE LOST OVERBOARD. ADDITIONAL CONTAINERS FROM HATCHES 1 AND 2 WERE LOST OVERBOARD AS THE VESSEL CONTINUED EAST. THE CONTAINER CONTAINING THIS MATERIAL WAS FOUND TO BE DAMAGED AND LEAKING ON ARRIVAL IN NEW ORLEANS.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

PART VIII – CONTACT INFORMATION

Contact's Name: JOE GALLEGO
Contact's Title: MGR CNT YARD SAFETY
Business Name and Address:

E-mail Address:
Telephone Number: 504-948-0245
Fax Number:
Hazmat Registration Number:
Date: 05/26/1998
Preparer is:



U.S. Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: I-1998061440
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/26/1998
4. Time of Incident (use 24-hour time): 11:55
5. Enter National Response Center Report Number (if applicable):
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: HOUSTON
County: FORT BEND
State: TX
Zip Code: (if known):
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
8. Mode of Transportation: Water
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: SEA-LAND SERVICE INC
Street: 2700 FRANCE ROAD
City: NEW ORLEANS
State: LA
Zip Code: 70126
Federal DOT Id Number:
Hazmat Registration Number:
11. Shipper/Officer:
Name: CONCENTRATE MFG CO OF PR THE
Street: PO BOX 1558
City: CIDRA PR
State: ZZ
Zip Code: 00739
Waybill/Shipping Paper: 796630887
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street: AVENDIA LA REFORMA 9-30
City: GUATEMALA
State: ZZ
Zip Code:
14. Proper Shipping Name of Hazardous Material: EXTRACTS, FLAVORING, LIQUID
15. Technical/Trade Name:
16. Hazardous Class/Division: Flammable - Combustible Liquid
17. Identification Number: (E.g. UN2764, NA 2020) UN1197

18. Packing Group: (if applicable)

19. Quantity Released: (Include Measurement Units) 2096 Liquid - Gallon

20. Was the material shipped as a hazardous waste?

If yes, provide the EPA Manifest Number:

21. Is this a Toxic by Inhalation (TIH) material?

If yes, provide the Hazard Zone:

22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate?

If yes, provide the Exemption, Approval, or CA number:

23. Was this an undeclared hazardous materials shipment?

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:

Non-Bulk

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: -

How Failed: -

Causes of Failure: -

26a. Provide the packaging identification markings, if available.

Identification Markings:

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Packaging Type:
Material of Construction:
Head Type (Drums only):

Packaging Type:
Material of Construction:

27. Describe the package capacity and the quantity:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Package Capacity: 4 Liquid - Gallon
Amount in Package:
Number in Shipment: 524
Number Failed: 524

Package Capacity: 1 Liquid - Gallon
Amount in Package:
Number in Shipment: 20996
Number Failed: 2096

28. Provide packaging construction and test information, as appropriate:

Manufacturer: NOT REPORTED BY CARRIER
Serial Number:
Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder)
Design Pressure: (if Tank Car, CTMV, Portable Tank)
Shell Thickness: (if Tank Car, CTMV, Portable Tank)
Head Thickness: (if Tank Car, CTMV)
Service Pressure: (if Cylinder)
If valve or device failed:
Type:
Model:
Manufacturer:

Manufacture Date:
Last Test Date:

29. If the packaging is for Radioactive Materials, complete the following:

Packaging Category:
Packaging Certification:
Certification Number:
Nuclide(s) Present:
Activity:
Critical Safety Index:

Transport Index:

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | False |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

Fire/EMS Report #:
Police Report #:
In-house cleanup:
Other Cleanup:

32. Damages Was the total damage cost more than \$500? False

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 0.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality? False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material? False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury? False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation? False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed? False

If yes, how many?

37. Was the material involved in a crash or derailment? False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

SEA-LAND SERVICE, INC. ISSUED A BILL OF LADING FOR THE TRANSPORTATION OF THIS CARGO. SEA-LAND CONTRACTED WITH MCALLISTER TOWING AND TRANSPORTATION COMPANY INC TO TRANSPORT THE CARGO ON THE HOUSTON TO NEW ORLEANS LEG OF THE CARRIAGE. THE CARGO WAS LOADED ABOARD MCALLISTER TOWING AND TRANSPORTATION COMPANY, INC.'S BARGE, THE CHESAPEAKE TRADER, AT HOUSTON AND SECURED WITH EQUIPMENT SUPPLIED BY COLUMBIA COASTAL TRANSPORT, LLC, TO THE SATIFICATION OF THE MASTER OF THE M/V CAPT BILL, THE TUG WHICH TOWED THE BARGE. THE M/V CAPT. BILL WAS CHARTERED FROM MCALLISTER TOWING AND TRANSPORTATION COMPANY INC. ALL DECISIONS REGARDING DEPARTURE TIME, ROUTE AND NAVIGATION OF THE TUG AND TOW WERE MADE BY THE MASTER OF THE VESSEL. SEA-LAND HAS NO FIRST HAND INFORMATION WITH REGARDS TO THE EVENTS FOLLOWING DEPARTURE OF THE TUG AND TOW FROM HOUSTON, UNTIL THE FLOTILLA'S ARRIVAL IN NEW ORLEANS. HOWEVER, REVIEW OF THE DECK LOG OF THE TUG CAPT. BILL INDICATES THAT 1155 HOURS ON SUNDAY, APRIL 26, 1998, WHILE THE VESSEL WAS LOCATED AT LATITUDE 28 46.9'N AND LONGITUDE 92 18.1'W, 9 CONTAINERS FROM HATCH 1 WERE LOST OVERBOARD. ADDITIONAL CONTAINERS FROM HATCHES 1 AND 2 WERE LOST OVERBOARD AS THE VESSEL CONTINUED EAST. THE CONTAINER CONTAINING THIS MATERIAL WAS FOUND TO BE DAMAGED AND LEAKING ON ARRIVAL IN NEW ORLEANS.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

PART VIII – CONTACT INFORMATION

Contact's Name: JOE GALLEGO
Contact's Title: MGR CNT YARD SAFETY
Business Name and Address:

E-mail Address:
Telephone Number: 504-948-0245
Fax Number:
Hazmat Registration Number:
Date: 05/26/1998
Preparer is:



U.S. Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: I-1998061440
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 04/26/1998
4. Time of Incident (use 24-hour time): 11:55
5. Enter National Response Center Report Number (if applicable):
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: HOUSTON
County: FORT BEND
State: TX
Zip Code: (if known):
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
8. Mode of Transportation: Water
9. Transportation Phase: In Transit
10. Carrier/Reporter:
Name: SEA-LAND SERVICE INC
Street: 2700 FRANCE ROAD
City: NEW ORLEANS
State: LA
Zip Code: 70126
Federal DOT Id Number:
Hazmat Registration Number:
11. Shipper/Officer:
Name: CHEMSOL S A
Street: 9009 NORTH LOOP EAST STE. 270
City: HOUSTON
State: TX
Zip Code: 77029
Waybill/Shipping Paper: 199304
Hazmat Registration Number:
12. Origin (if different from shipper address)
Street:
City:
State:
Zip Code:
13. Destination:
Street:
City: SAN SALVADOR
State: ZZ
Zip Code:
14. Proper Shipping Name of Hazardous Material: ETHYLENE GLYCOL MONOETHYL ETHER ACETATE
15. Technical/Trade Name: ETHYLENE GLYCOL
16. Hazardous Class/Division: Flammable - Combustible Liquid
17. Identification Number: (E.g. UN2764, NA 2020) UN1172

18. Packing Group: (if applicable)

19. Quantity Released: (Include Measurement Units) 55 Liquid - Gallon

20. Was the material shipped as a hazardous waste?

If yes, provide the EPA Manifest Number:

21. Is this a Toxic by Inhalation (TIH) material?

If yes, provide the Hazard Zone:

22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate?

If yes, provide the Exemption, Approval, or CA number:

23. Was this an undeclared hazardous materials shipment?

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:

Non-Bulk

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: -

How Failed: -

Causes of Failure: -

26a. Provide the packaging identification markings, if available.

Identification Markings:

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Packaging Type:
Material of Construction:
Head Type (Drums only):

Packaging Type:
Material of Construction:

27. Describe the package capacity and the quantity:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Package Capacity: 55 Liquid - Gallon
Amount in Package:
Number in Shipment: 63
Number Failed: 1

Package Capacity:
Amount in Package:
Number in Shipment:
Number Failed:

28. Provide packaging construction and test information, as appropriate:

Manufacturer: NOT REPORTED BY CARRIER
Serial Number:
Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder)
Design Pressure: (if Tank Car, CTMV, Portable Tank)
Shell Thickness: (if Tank Car, CTMV, Portable Tank)
Head Thickness: (if Tank Car, CTMV)
Service Pressure: (if Cylinder)
If valve or device failed:
Type:
Model:
Manufacturer:

Manufacture Date:
Last Test Date:

29. If the packaging is for Radioactive Materials, complete the following:

Packaging Category:
Packaging Certification:
Certification Number:
Nuclide(s) Present:
Activity:
Critical Safety Index:

Transport Index:

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | False |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

Fire/EMS Report #:
Police Report #:
In-house cleanup:
Other Cleanup:

32. Damages Was the total damage cost more than \$500? False

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 0.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality? False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:
Responders:
General Public:

33b. Were there human fatalities that did not result from the hazardous material? False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury? False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:
Responders:
General Public:

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:
Responders:
General Public:

35. Did the hazardous material cause or contribute to an evacuation? False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated: 0
Duration of the evacuation:

36. Was a major transportation artery or facility closed? False

If yes, how many?

37. Was the material involved in a crash or derailment? False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

SEA-LAND SERVICE, INC. ISSUED A BILL OF LADING FOR THE TRANSPORTATION OF THIS CARGO. SEA-LAND CONTRACTED WITH MCALLISTER TOWING AND TRANSPORTATION COMPANY INC TO TRANSPORT THE CARGO ON THE HOUSTON TO NEW ORLEANS LEG OF THE CARRIAGE. THE CARGO WAS LOADED ABOARD MCALLISTER TOWING AND TRANSPORTATION COMPANY, INC.'S BARGE, THE CHESAPEAKE TRADER, AT HOUSTON AND SECURED WITH EQUIPMENT SUPPLIED BY COLUMBIA COASTAL TRANSPORT, LLC, TO THE SATIFICATION OF THE MASTER OF THE M/V CAPT BILL, THE TUG WHICH TOWED THE BARGE. THE M/V CAPT. BILL WAS CHARTERED FROM MCALLISTER TOWING AND TRANSPORTATION COMPANY INC. ALL DECISIONS REGARDING DEPARTURE TIME, ROUTE AND NAVIGATION OF THE TUG AND TOW WERE MADE BY THE MASTER OF THE VESSEL. SEA-LAND HAS NO FIRST HAND INFORMATION WITH REGARDS TO THE EVENTS FOLLOWING DEPARTURE OF THE TUG AND TOW FROM HOUSTON, UNTIL THE FLOTILLA'S ARRIVAL IN NEW ORLEANS. HOWEVER, REVIEW OF THE DECK LOG OF THE TUG CAPT. BILL INDICATES THAT 1155 HOURS ON SUNDAY, APRIL 26, 1998, WHILE THE VESSEL WAS LOCATED AT LATITUDE 28 46.9'N AND LONGITUDE 92 18.1'W, 9 CONTAINERS FROM HATCH 1 WERE LOST OVERBOARD. ADDITIONAL CONTAINERS FROM HATCHES 1 AND 2 WERE LOST OVERBOARD AS THE VESSEL CONTINUED EAST. THE CONTAINER CONTAINING THIS MATERIAL WAS FOUND TO BE DAMAGED AND LEAKING ON ARRIVAL IN NEW ORLEANS.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

PART VIII – CONTACT INFORMATION

Contact's Name: JOE GALLEGO
Contact's Title: MGR CNT YARD SAFETY
Business Name and Address:

E-mail Address:
Telephone Number: 504-948-0245
Fax Number:
Hazmat Registration Number:
Date: 05/26/1998
Preparer is: