



U.S. Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: I-2015080028
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 06/25/2015
4. Time of Incident (use 24-hour time): 03:30
5. Enter National Response Center Report Number (if applicable):
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
City: FREEMONT
County: SANDUSKY
State: OH
Zip Code: (if known): 43420
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
2323 COMMERCE DR.
8. Mode of Transportation: Highway
9. Transportation Phase: Unloading
10. Carrier/Reporter:
Name: PVS-NOLWOOD CHEMICALS, INC.
Street: 10900 HARPER AVE
City: DETROIT
State: MI
Zip Code: 48213
Federal DOT Id Number: 200721
Hazmat Registration Number: 060215552077X
11. Shipper/Officer:
Name: PVS-NOLWOOD CHEMICALS, INC.
Street: 10900 HARPER AVENUE
City: DETROIT
State: MI
Zip Code: 48213
Waybill/Shipping Paper: 464686-2
Hazmat Registration Number: 060215552077X
12. Origin (if different from shipper address)
Street: 9000 HUBBELL AVE
City: Detroit
State: MI
Zip Code: 48228
13. Destination:
Street: 2323 COMMERCE DR
City: Fremont
State: OH
Zip Code: 43420
14. Proper Shipping Name of Hazardous Material: SODIUM HYDROXIDE, SOLUTION
15. Technical/Trade Name:
16. Hazardous Class/Division: Corrosive Material
17. Identification Number: (E.g. UN2764, NA 2020) UN1824

18. Packing Group: (if applicable) II

19. Quantity Released: (Include Measurement Units) 12 Liquid - Gallon

20. Was the material shipped as a hazardous waste? False
If yes, provide the EPA Manifest Number:

21. Is this a Toxic by Inhalation (TIH) material? False
If yes, provide the Hazard Zone:

22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate? True
If yes, provide the Exemption, Approval, or CA number: SP-12412

23. Was this an undeclared hazardous materials shipment? False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:
IBC

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.
Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: -
How Failed: -
Causes of Failure: -

26a. Provide the packaging identification markings, if available.

Identification Markings: NO MARKINGS GIVEN

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Packaging Type:
Material of Construction:
Head Type (Drums only):

Packaging Type:
Material of Construction:

27. Describe the package capacity and the quantity:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Package Capacity: 0
Amount in Package: 0
Number in Shipment: 1
Number Failed: 0

Package Capacity:
Amount in Package:
Number in Shipment:
Number Failed:

28. Provide packaging construction and test information, as appropriate:

Manufacturer:
Serial Number:
Material of Construction: (if Tank Car, CTMV, Portable Tank, or Cylinder)
Design Pressure: (if Tank Car, CTMV, Portable Tank)
Shell Thickness: (if Tank Car, CTMV, Portable Tank)
Head Thickness: (if Tank Car, CTMV)
Service Pressure: (if Cylinder)
If valve or device failed:
Type:
Model:
Manufacturer:

Manufacture Date:
Last Test Date:

29. If the packaging is for Radioactive Materials, complete the following:

Packaging Category:
Packaging Certification:
Certification Number:
Nuclide(s) Present:
Activity:
Critical Safety Index:

Transport Index:

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|-------|
| - Spillage: | True | - Fire: | False |
| - Explosion: | False | - Material Entered Waterway/Storm Sewer: | False |
| - Vapor (Gas) Dispersion: | False | - Environmental Damage: | False |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

- Fire/EMS Report #: False
Police Report #: False
In-house cleanup: True
Other Cleanup: False

32. Damages Was the total damage cost more than \$500?

False

If yes, enter the following information: (If no, go to question 33.)

Material Loss: \$ 0.00
Carrier Damage: \$ 0.00
Property Damage: \$ 0.00
Response Cost: \$ 0.00
Remediation/Cleanup Cost: \$ 0.00
(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality?

False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees: 0
Responders: 0
General Public: 0

33b. Were there human fatalities that did not result from the hazardous material?

False

If yes, how many? 0

34. Did the hazardous material cause or contribute to personal injury?

True

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees: 1
Responders: 0
General Public: 0

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees: 1
Responders: 0
General Public: 0

35. Did the hazardous material cause or contribute to an evacuation?

False

If yes, provide the following information:

Total number of general public evacuated:
Total number of employees evacuated:
Total evacuated:
Duration of the evacuation:

36. Was a major transportation artery or facility closed?

False

If yes, how many?

37. Was the material involved in a crash or derailment?

False

If yes, provide the following information:

Estimated speed (mph):
Weather conditions:
Vehicle overturned?
Vehicle left roadway/track?

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

PVS-Nolwood was transferring 50% sodium hydroxide to the customer's 1000 gallon storage tank. PVS-Nolwood was pumping product from IBC's to the customer tank using an air diaphragm pump. Product was released from the tank overflow pipe and into the tank secondary containment. The pump was shut down immediately. Approximately 1-2 gallons was discharged into the tank's secondary containment. The hose used to fill the 1000 gallon tank was filled with 50% sodium hydroxide and needed to be purged of product. During the purge process 8-10 gallons of product was released into the box trailer and the customer's shop floor. Absorbent pads were used to soak up liquid product.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

1. Review and update unloading process at customer site 2. Review and update as needed the driver safety checklist 3. Train drivers on updated process and procedure as appropriate 4. Review and discuss tank capacity and transfer operations with material transfer personnel 5. Review Stop Work activities or actions with material transfer personnel

PART VIII – CONTACT INFORMATION

Contact's Name:	RICHARD SMALLETS
Contact's Title:	REGULATORY COMPLIANCE SPECIALIST
Business Name and Address:	PVS-NOLWOOD CHEMICALS, INC. 10900 HARPER AVE DETROIT MI 48213
E-mail Address:	rsmallets@pvschemicals.com
Telephone Number:	313 272 0993
Fax Number:	313 272 3263
Hazmat Registration Number:	060215552077X
Date:	07/24/2015
Preparer is:	Carrier