



U.S. Department of Transportation
Research and Special Programs Administration

Hazardous Materials Incident Report

Form Approval OMB No. 3137-0039

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 2137-0039. The filling out of this information is mandatory and will take 96 minutes to complete.

INSTRUCTIONS

Submit this report to the Information Systems Manager, U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety, DHM-63, Washington, D.C. 20590-0001. If space provided for any item is inadequate, use a separate sheet of paper, identifying the entry number being completed. Copies of this form and instructions can be obtained from the Office of Hazardous Materials Website at <http://hazmat.dot.gov>. If you have any questions, you can contact the Hazardous Materials Information Center at 1-800-HMR-4922 (1-800-467-4922) or online at <http://hazmat.dot.gov>.

PART I - REPORT TYPE

1. Incident Id: X-2017030271
2. This is to report: A

PART II - GENERAL INCIDENT INFORMATION

3. Date of Incident: 01/18/2017
4. Time of Incident (use 24-hour time): 19:30
5. Enter National Response Center Report Number (if applicable):
6. If you submitted a report to another Federal DOT agency, enter the agency and report number:
7. Location of Incident:
- City: Geismar
County: ASCENSION
State: LA
Zip Code: (if known): 70734
Street Address/Mile Marker/Yard Name/Airport/Body of Water/River Mile:
8. Mode of Transportation: Rail
9. Transportation Phase: In Transit
10. Carrier/Reporter:
- Name: CN / Illinois Central Railroad
Street: 17641 South Ashland Avenue
City: Homewood
State: IL
Zip Code: 60430-1345
Federal DOT Id Number: CN103
Hazmat Registration Number: 052016001018Y
11. Shipper/Officer:
- Name: REAGENT CHEMICAL + RESEARCH
Street: 36335 HIGHWAY 30
City: Geismar
State: LA
Zip Code: 70734
Waybill/Shipping Paper: 484039
Hazmat Registration Number:
12. Origin (if different from shipper address)
- Street: 36335 HIGHWAY 30
City: Geismar
State: LA
Zip Code: 70734
13. Destination:
- Street: 5850 LOCUST ROAD
City: Cedar Rapids
State: IA
Zip Code: 52404
14. Proper Shipping Name of Hazardous Material: HYDROCHLORIC ACID
15. Technical/Trade Name:
16. Hazardous Class/Division: Corrosive Material
17. Identification Number: (E.g. UN2764, NA 2020) UN1789

18. Packing Group: (if applicable) II

19. Quantity Released: (Include Measurement Units) 19867 Liquid - Gallon

20. Was the material shipped as a hazardous waste? False
If yes, provide the EPA Manifest Number:

21. Is this a Toxic by Inhalation (TIH) material? False
If yes, provide the Hazard Zone:

22. Was the material shipped under an Exemption, Approval, or Competent Authority Certificate? False
If yes, provide the Exemption, Approval, or CA number:

23. Was this an undeclared hazardous materials shipment? False

PART III - PACKAGING INFORMATION

24. Check Packaging Type (check only one - if more than one, list type of packaging, copy Part III, and complete for each type:

Tank Car

25. See instructions and enter the appropriate failure codes found at the end of the instructions. Be sure to enter the codes from the list that corresponds to the particular packaging type checked above. Enter the number of codes as appropriate to describe the incident.

Enter the most important failure point in line 1. If there are more than two failure points, provide in this format in part VI.

What Failed: - 149-Tank Head

How Failed: - 309-Punctured

Causes of Failure: - Vehicular Crash or Accident Damage

26a. Provide the packaging identification markings, if available.

Identification Markings: 111A100W5

(Examples: 1A1/Y1.4/150/92/USA/RB/93/RL, UN31H1/Y0493/USA/M9339/10800/1200, DOT - 105A - 100W (RAIL), DOT 406 (HIGHWAY), DOT 51, DOT 3-A)

26b. For Non-bulk, IBC, or non-specification packaging, if identification markings are incomplete or unavailable, see instructions and complete the following:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Packaging Type:
Material of Construction:
Head Type (Drums only):

Packaging Type:
Material of Construction:

27. Describe the package capacity and the quantity:

Single Package or Outer Packaging:

Single Package or Inner Packaging (if any):

Package Capacity: 20703 Liquid - Gallon
Amount in Package: 20167 Liquid - Gallon
Number in Shipment: 1
Number Failed: 1

Package Capacity:
Amount in Package:
Number in Shipment:
Number Failed:

28. Provide packaging construction and test information, as appropriate:

Manufacturer:	RICRIC	Manufacture Date:	08/30/1977
Serial Number:	RCRX1024	Last Test Date:	12/31/2015
Material of Construction:	ASTM A515, GR. 70 (if Tank Car, CTMV, Portable Tank, or Cylinder)		
Design Pressure:	100 (if Tank Car, CTMV, Portable Tank)		
Shell Thickness:	(if Tank Car, CTMV, Portable Tank)		
Head Thickness:	(if Tank Car, CTMV)		
Service Pressure:	(if Cylinder)		
If valve or device failed:			
Type:			
Model:			
Manufacturer:			

29. If the packaging is for Radioactive Materials, complete the following:

Packaging Category:	
Packaging Certification:	
Certification Number:	
Nuclide(s) Present:	Transport Index:
Activity:	
Critical Safety Index:	

PART IV – CONSEQUENCES

30. Result of Incident (check all that apply):

- | | | | |
|---------------------------|-------|--|--|
| - Spillage: | True | - Fire: | |
| - Explosion: | | - Material Entered Waterway/Storm Sewer: | |
| - Vapor (Gas) Dispersion: | | - Environmental Damage: | |
| - No Release: | False | | |

31. Emergency Response: The following entities responded to the incident: (Check all that apply)

Fire/EMS Report #: ☐
Police Report #: True 17-00294
In-house cleanup: True
Other Cleanup: True

32. Damages Was the total damage cost more than \$500? True

If yes, enter the following information: (If no, go to question 33.)

Material Loss:	\$ 19,867.00
Carrier Damage:	\$ 0.00
Property Damage:	\$ 0.00
Response Cost:	\$ 0.00
Remediation/Cleanup Cost:	\$ 0.00

(See damage definitions in the instructions)

33a. Did the hazardous material cause or contribute to a human fatality? False

If yes, enter the number of fatalities resulting from the hazardous material:

Employees:	
Responders:	
General Public:	

33b. Were there human fatalities that did not result from the hazardous material? False

If yes, how many?

34. Did the hazardous material cause or contribute to personal injury? False

If yes, enter the number of injuries resulting from the hazardous material:

Hospitalized (Admitted Only):

Employees:	
Responders:	
General Public:	

Non-Hospitalized:

(e.g.: On site first aid or Emergency Room observation and release)

Employees:	
Responders:	
General Public:	

35. Did the hazardous material cause or contribute to an evacuation? False

If yes, provide the following information:

Total number of general public evacuated:	
Total number of employees evacuated:	
Total evacuated:	
Duration of the evacuation:	

36. Was a major transportation artery or facility closed? False

If yes, how many?

37. Was the material involved in a crash or derailment? True

If yes, provide the following information:

Estimated speed (mph):	14
Weather conditions:	DARK
Vehicle overturned?	False
Vehicle left roadway/track?	False

PART V - AIR INCIDENT INFORMATION (please refer to S 175.31 to report a discrepancy for air shipments)

38. Was the shipment on a passenger aircraft?

If yes, was it tendered as cargo, or as passenger baggage?

39. Where did the incident occur (if unknown, check the appropriate box for the location where the incident was discovered)?

40. What phase(s) had the shipment already undergone prior to the incident? (Check all that apply)

- | | |
|--|--|
| - Shipment had not been transported | - Transported by air (first flight) |
| - Transport by air (subsequent flights) | - Initial transport by highway to cargo facility |
| - Transfer at sort center/cargo facility | |

PART VI - DESCRIPTION OF EVENTS & PACKAGE FAILURE

- Describe the sequence of events that led to the incident and the actions taken at the time it was discovered. Describe the package failure, including the size and location of holes, cracks, etc. Photographs and diagrams should be submitted if needed for clarification. Estimate the duration of the release, if possible. Describe what was done to mitigate the effects of the release. Continue on additional sheets if necessary.

Describe:

During switching operations on the north end of the CN Geismar yard located in Geismar, Louisiana, tank car HOKX 286084 (Residue Sodium Hydroxide Solution / UN 1824 / Class 8) collided with tank car RCRX 1024 (Load Hydrochloric Acid / UN 1789 / Class 8) resulting in a release in product from tank car RCRX 1024. All appropriate departments were notified and tank car was isolated. CNs response team responded observing a large hole in the head of tank car RCRX 1024. The product lost to the ground was contained to the site and was neutralized before remediation. All remaining product in the car was recovered for shipment or disposal.

PART VII - RECOMMENDATIONS/ACTIONS TAKEN TO PREVENT RECURRENCE

- Where you are able to do so, suggest or describe changes (such as additional training, use of better packaging, or improved operating procedures) to help prevent recurrence. Provide recommendations for improvement to hazardous materials transportation beyond the control of your individual company. Continue on additional sheets if necessary.

Describe:

No additional comments.

PART VIII – CONTACT INFORMATION

Contact's Name:	Christine Gatti
Contact's Title:	Dangerous Goods Specialist
Business Name and Address:	CN / Illinois Central Railroad 17641 South Ashland Avenue Homewood IL 60430-1345
E-mail Address:	christine.gatti@cn.ca
Telephone Number:	514-399-4414
Fax Number:	514-399-7427
Hazmat Registration Number:	052016001018Y
Date:	
Preparer is:	Carrier

08/30/1977